

MOT

TID



EASTSIDE MITSUBISHI 303 WHITEHORSE ROAD NUNAWADING VIC 3131



EastSide Mitsubishi Eastside Dealership Investments Pty Ltd PO Box 3575, Nunawading, Victoria 3131

303 Whitehorse Road, Nunawading, Victoria 3131 Phone: (03) 9878 7333 Fax: (03) 9878 6149 ABN 41 391 506 581 ACN 132 373 132 LMCT 10537

Service	MID DATE/TIME	23465115 05/07/23 15:49	www.eastsidemitsubishi.com.au							
Customer No.		05/07/25 15,49					Doc #: EMC	SW11	144	
4952416 Doc Date 05/07/23 Reg No. AWV297	RRN STAN 004194 CARD 1563 VISA	051549004194 AUTH 174821 CR(M)		Advisor John Kenworthy 62 Year / Make / Model 18/MITSUBISHI/YA Eclips Model No	201 se Cross		IUM/BLA	Team SER Tag N 21	RVICI	E
Stock No.	МОТО	AUD 1,300.00		YA2T45		SE CR		Eng./	AUT	- 1
YA2448; Purchase Or	APPROVED	0000	act No	JMFXTGK1WJZ00758	Kilometre 89951	5	Prod Date 11/06/18	Orig.	Del. D 02/19	
☐ CASH	C		66701 Terms	Contract Name HARRIER STD	Contract 17500	Exp. Kms 0	Exp Date 26/02/29			
CHEC CRED	CUSTOMER COPY		Cash	Selling Dealer V282	25		Delivery Date 25/02/19	Warr. Exp. Date 25/02/24		
Customer M			Q2511	Date & Time Promised 05/07/23 04:30pm	7 me Red 07:30		Quote Price	Air Y	_	Turb
0407887787	7	1		Cust Email		Driver Mot	p#			
Oriver Email				michelle.riley@live.com.a	u					
ahour	0									

Job# 1

Operation

Description

Amount

Tech(s): 6212 90,000km/72mth service (ModelYr: 2018-2019, OPT: With Distance Based Servicing) 517.59

Customer Instructions:

Carried out 90,000km/72 month service as per handbook.

--- Under The Hood ---

Checked drive belt and adjusted tension as required.

Checked air intake & turbocharger oil hoses.

Replaced spark plugs.

Inspected valve clearances (adjustment at extra cost).

Inspected cooling system, hoses and connections.

Checked coolant level.

Replaced air filter element.

Replaced brake fluid.

Checked battery terminals for cleanliness and security.

Checked battery electrolyte specific gravity, level & condition usi

--- Under The Vehicle --

Inspected suspension & steering components for damage/wear.

Inspected ball joints, seals, bushes & boots.

Inspected drive shafts including CV boots.

Replaced transmission fluid, CVT.

Replaced engine oil & oil filter.

Inspected fuel pipes, hoses and connections for leaks.

Inspected exhaust system for security and leaks.

Checked under body for damage & condition.

--- Inside The Vehicle --

Checked brake pedal travel.

Checked & adjusted park brake as required.

Replaced fresh air/pollen filter.

--- Outside The Vehicle --

Inspected brake pads and discs.

Checked brake hoses & pipes for damage, corrosion & leaks.

Checked wheel alignment (visual inspection for tyre wear).

Checked condition and pressures of all tyres including spare.

--- Final Inspections & Road Test ---

Checked engine idle speed.

Inspected the body of the vehicle for any damage.

Inspected seat belts.

Checked lights, wiper/washers, horn and electrical systems.

Checked vehicle for outstanding recall or service campaigns.

NON	GE	NUIN	E PA	RTS

Genuine Mitsubishi parts and ac ries are identified by the words 'Genume Parts' or 'Value Selection Parts' alongside th Mitsubish Motors Diamond Logo.

heres not identified in this way are not genuine Mitsubishi products. Please note that any non-genuine parts, accessories, products ree are not covered by the Mitsubishi warranty. Use of such products may affect the Mitsubishi warranty to the extent that une products may compromise the performance, safety or quality of your Mitsubishi vehicle or may cause the use of such non-gr age to your vehicle.

OWNER	DRIVER	SIGNATURE:	