

# TAX INVOICE

Tax Invoice Number: 231197

Date: 07/12/2023

Due Date: 07/12/2023



290 Old Geelong Road  
Hoppers Crossing Victoria 3029

ABN: 11639128733

Tel: 03 8368 2044

Email:

[hopperscrossing@autoplus.com.au](mailto:hopperscrossing@autoplus.com.au)

Website:

<https://www.autoplus.com.au/mechanic/hoppers-crossing-car-service>

**BILL TO:**

**Nitin**

17 Watersedge Cove

Point Cook Victoria 3030

Tel: 0451101101

Email:

[nitin.ukunde@gmail.com](mailto:nitin.ukunde@gmail.com)

**FOR:**

Vehicle pickup & drop off

Odometer: 90,047 Kms

Make	Model/Year	Body Type	Reg No.	Fleet No.	VIN
Honda	Odyssey/2016	Wagon	1IE1VP		JHMRC1830GC205610

Description	Qty.	Unit Price	GST	Amount
<b>PETROL LOGBOOK SERVICE</b>				
Pro Low SAPS C3 5W30 ENGINE OIL	6.0	\$0.00	\$0.00	\$0.00
Oil Filter	1.0	\$0.00	\$0.00	\$0.00
Sump Plug Washer - Oil Ring	1.0	\$0.00	\$0.00	\$0.00
Windscreen Washer Additive	1.0	\$0.00	\$0.00	\$0.00
CW-Touch Free Car Wash and the Air Freshener	1.0	\$0.00	\$0.00	\$0.00
Environmental Waste Removal	1.0	\$0.00	\$0.00	\$0.00
Work Shop Supplies	1.0	\$0.00	\$0.00	\$0.00
Labour Charges for Inspection, Service and Lube	1.0	\$209.00	\$19.00	\$209.00
<b>ADDITIONAL SERVICE ITEMS</b>				
AF - Air Filter	1.0	\$52.00	\$4.73	\$52.00
CB - Cabin Filter	1.0	\$65.00	\$5.91	\$65.00
WB - Wiper Blades Front	2.0	\$20.00	\$3.64	\$40.00
<b>Suspension &amp; Shock Absorbers Front</b>				
BI001 Supplied & Fitted Front shock absorbers	2.0	\$330.00	\$60.00	\$660.00
Labour - Front Shock Absorbers	1.0	\$140.00	\$12.73	\$140.00
Wheel Alignment - Standard	1.0	\$100.00	\$9.09	\$100.00

Log Book Service:  
 Carry out service as per manufacturer's specifications.  
 Complete Safety Inspection report sheet - AutoPlus  
 Replaced Front wiper blades  
 Drain Engine Oil and replace Engine Oil Filter  
 Replace Sump Plug Washer  
 Check front and rear brake pads and discs  
 Front Brake 10% Rear Brake 10% need replacing  
 Check suspension components for signs of wear  
 Top up all fluid levels  
 Check Battery and charging system  
 Battery needs replacement (235.00) Fitted  
 Diagnostic Scan and Report  
 Check Tyres and Pressures - Reset Tyre Pressure monitoring system where required  
 Reset service reminder indicator  
 Replace service sticker  
 Update service books and stamp

RECOMMENDATIONS:-  
 Needs Front and rear brakes  
 Needs 4 tyres 215/55R17  
 Requires at this time OF INSPECTION:  
 Front Disc Pads and Disc machine (437.00)  
 Rear Disc Pads and Disc machine (437.00)

<b>Subtotal</b>	<b>\$1,150.91</b>
<b>GST</b>	<b>\$115.09</b>
<b>Total</b>	<b>\$1,266.00</b>
<b>Paid</b>	<b>\$0.00</b>
<b>Balance Due</b>	<b>\$1,266.00</b>