



TAX INVOICE

Catherine Swale
Heritage Cove
MAYLANDS WA 6051
AUSTRALIA

Invoice Date
9 Apr 2024

JDL Automotive
JDLAutos@outlook.com

Invoice Number
INV-0350

0407265040

Reference
Toyota Corolla - 1EWK957
- 195029km

ABN
12 417 589 147

Description	Quantity	Unit Price	GST	Amount AUD
Call out/diagnostic fee:	1.00	70.00	10%	70.00
- Attend vehicle with the abs light flashing, scanned computer and found LHF wheel speed sensor fault and alternator overcharging fault				
- Checked LHF wheel speed sensor and found that the sensor wiring had been damage and inner guard liner was missing - Recommend replacing damaged sensor and fitting new inner guard liner				
- Checked alternator charge rate and found that it was charging at 20V - Recommend replacing alternator				
Standard service:	1.00	220.00	10%	220.00
- 4.2L Castrol Magnatec Stop-Start 10W-30 Engine Oil				
- 1 x R2620p Oil filter				
- 1 x Sump plug washer				
- Vehicle safety inspection				
Supply and fit alternator	1.00	570.00	10%	570.00
- Supply and fit LHF wheel speed sensor	1.00	300.00	10%	300.00
- Found that the other piece of the wiring harness was also damaged and require repairing - Repaired (extra \$30)				
- Erased fault codes and test drive - all ok				
- Replaced RHR park light globe	1.00	15.00	10%	15.00

ITEMS OF CONCERN:

- RH engine mount has sagged - Recommend replacing
- Rear wiper is splitting - Recommend replacing
- Cabin filter is dirty - Recommend replacing

Description	Quantity	Unit Price	GST	Amount AUD
- Air filter is dirty - Recommend replacing				
- Engine idle is low and hunting - Recommend throttle body and induction clean				
- Spark plugs are worn - Recommend replacing				
- Brake fluid is high in moisture - Recommend flushing				
- Front brakes are 70% worn - Recommend replacing next service				
- Starter motor is staying partially engaged for a brief moment after engine starts, causing a terrible crunching noise - Recommend replacing				
- Minor oil leak present from timing cover area - Monitor				
- All shock absorbers are getting weak - Can monitor for now				
- LHF inner guard liner is missing- Recommend fitting a new liner				
			INCLUDES GST 10%	106.81
			TOTAL AUD	1,175.00

Due Date: 9 Apr 2024

Payment Details:

Account name: JDL Automotive

BSB: 066-128

Account: 10835787

Reference number: Quote invoice number

✂

PAYMENT ADVICE

To: JDL Automotive
 JDLAutos@outlook.com
 0407265040

Customer	Catherine Swale
Invoice Number	INV-0350
Amount Due	1,175.00
Due Date	9 Apr 2024

Amount Enclosed

Enter the amount you are paying above