



**U9, 65-75 Mark Street**  
**North Melbourne Victoria 3051**  
**ABN:** 60 160 753 882  
**Tel:** 03 9329 9973  
**Email:** service@germanteknik.com.au  
**Website:** www.germanteknik.com.au

**BILL TO:**  
**Peter Higgs**  
52 The Ridgeway  
Kensington Victoria 3031  
**Tel:** Heather 0421 510 100  
**Email:** higgspeter@gmail.com

### TAX INVOICE

**Tax Invoice Number:** 24GT14937  
**Date:** 22/04/2024  
**Due Date:** 22/04/2024

**FOR:**  
**Odometer:** 220,105 Kms  
**Key Tag:** 6

**Model:** Volkswagen Polo 6R  
**Reg No:** YJE194  
**Next Service Date:** 23/04/2025  
**Next Service Odometer:** 235,105 Kms  
**VIN:** WVVZZZ6RZBU027522  
**Body Type:** 4DR Hatch  
**Year:** 2011

Description	Qty.	Unit Price	Amount
<b>Basic-Service 15/45/75/105K 1.2 TSI Polo 6R, Golf 6, Skoda and Audi</b>			<b>\$0.00</b>
<b>STANDARD YEARLY SERVICE INSPECTION</b>			
Carry out 12 Month Vehicle Inspection Service			
Replace engine oil and filter			
Check cooling system			
Check battery/charge system			
Check all fluid levels			
Check steering and suspension			
Check front and rear brakes			
Check park brake			
Check all seat belts			
Check all tyres, tyre pressures, lights, washers and wipers			
Lubricate door locks and hinges			
Scan vehicles ECU for faults and reset service indicators			
Update service book			
Road Test vehicle			

<b>IN ADDITION</b>			<b>\$868.94</b>
<b>Replace fuel filter.</b>			
<b>Replace cabin filter element.</b>			
Castrol edge Longlife prof III 5-30 VW 504 00	4.75	\$26.45	\$125.64
Hengst oil filter Polo 1.2/1.4 TSI	1.0	\$41.50	\$41.50
Sump Plug Washer	1.0	\$2.50	\$2.50
Environmental Waste Disposal	1.0	\$15.75	\$15.75
Workshop Sundries	1.0	\$22.95	\$22.95
Wurth Windscreen additive 5ltr-summer	1.0	\$11.85	\$11.85
Hengst fuel filter Polo/Golf A3/5	1.0	\$99.00	\$99.00
Cabin Filter Polo 6R/A1	1.0	\$68.50	\$68.50
LABOUR SPECIALISED			\$481.25
<b>Brake fluid flush Dot 4</b>			
<b>Extract fluid from reservoir, clean filter where possible. Flush system with flushing machine and new Castrol brake fluid</b>			
			<b>\$160.75</b>
Castrol Dot 4 Brake fluid	1.0	\$29.50	\$29.50
LABOUR SPECIALISED			\$131.25
<b>Brakes-Rear</b>			<b>\$642.33</b>
<b>Where applicable wind back electronic park brake motors with scanner. Remove excess brake fluid</b>			
<b>Remove and refit brake callipers, calliper carriers.</b>			
<b>Replace rear brake pads and rotors.</b>			
<b>Reset callipers, carry out road test and bedding in procedure.</b>			
Brake Rotor Rear Golf 4/A3/Polo 6R	2.0	\$108.88	\$217.76
Brake pad rear VAG	1.0	\$118.32	\$118.32
LABOUR SPECIALISED			\$306.25

Minor engine oil sweats from timing chain covers, 4/10 at this stage.  
Spark plugs were not replaced as leads are stuck to plugs and would damage leads on removal.

<b>Subtotal</b>	<b>\$1,520.02</b>
<b>GST</b>	<b>\$152.00</b>
<b>Total</b>	<b>\$1,672.02</b>
<b>Paid</b>	<b>\$0.00</b>
<b>Balance Due</b>	<b>\$1,672.02</b>

Thank you for choosing German Technik.

If you like our Service, please review your experience on Facebook: [www.facebook.com/germanteknik](http://www.facebook.com/germanteknik) or Google+

EFT details:  
BSB: 063-162  
Account: 1054 1770  
Account Name: TLC Automotive Pty Ltd