



6/9 Newspaper Place
Maroochydore Queensland 4558
ABN: 34 639 399 009
Tel: (07) 54437311
Email: premiumauto.maroochydore@gmail.com
Website: www.premiumautomotive.com

Tax Invoice Number: 5542
Date: 28/11/2023
Due Date: 28/11/2023
Payment Term: COD
Saleperson:

BILL TO:
Stefan [REDACTED]
[REDACTED]
[REDACTED]

FOR:
100,000 MHS
Odometer: 99,637 Kms
Model: Nissan Pulsar
Reg No: 587GH6
Next Service Date: 27/05/2024
VIN: MNTFAAC12A0005701
Body Type: HATCH BACK
Year: 2014

Description	Qty.	Unit Price	GST	Amount
CUSTOMER REQUIREMENTS Check & inspect the following items requested by customer: - Carry out a logbook service as requested. - No concerns reported by customer.				
MANUFACTURERS HANDBOOK SERVICE Carry out Manufacturers Handbook service as specified by the vehicle's manufacturer. Carry out service of vehicle as required; Road test of vehicle carried out to test and check drivability. All fluids checked and topped up, check and report all components of vehicle. All service components specified by the manufacturer carried out including engine oil + oil filter renewal. 50 point vehicle safety check also carried out including windscreen clean and interior vacuum. Please refer to the technicians notes on the bottom of the invoice for any noted issues or recommendations of the vehicle.				
WORK - WORKSHOP CONSUMABLES	1.0	\$15.00	\$1.36	\$15.00
EPA - ENVIRONMENTAL LEVY	1.0	\$13.50	\$1.23	\$13.50
SPW - SUMP PLUG WASHER	1.0	\$3.50	\$0.32	\$3.50
WWA - WINDSCREEN WASHER ADDITIVE	1.0	\$2.00	\$0.18	\$2.00
65901 - WYNN'S ENGINE FLUSH	1.0	\$32.00	\$2.91	\$32.00
WACF0196 - CABIN FILTER	1.0	\$55.50	\$5.05	\$55.50
LZKAR6AP-11 - SPARK PLUG - PLATINUM	4.0	\$42.00	\$15.27	\$168.00

HT436 - HIGH-TECH OIL FILTER	1.0	\$23.50	\$2.14	\$23.50
HI1-2123-0200 - HI-TECH 10W/40 ENGINE OIL	4.0	\$20.50	\$7.45	\$82.00
LAB / C.B - LABOUR P/H - C.B			\$26.77	\$294.50
THROTTLE BODY / INLET SYSTEM CLEAN				
Carry out throttle body / air intake system clean to remove carbon deposits from inlet system, manifold and valves.				
60825 - WYNN'S EGR3 PETROL AIR INTAKE CLEANER	1.0	\$75.00	\$6.82	\$75.00
LAB / Z.G - LABOUR P/H - Z.G			\$7.05	\$77.50

*****TECHNICIANS NOTES*****
- No service book found in vehicle
- Coolant glycol level;
- Brake fluid moisture level; 1%
- Power steering fluid condition; N/A; Electric
- Tie rod end boot perishing. (minor) please monitor next service.

*****BATTERY TEST*****
Battery charge rating - 76%
Battery health rating -100%

*****TYRES & BRAKES*****
Front tyre tread depths - 4mm
Rear tyre tread depth - 4mm
Front brake pad thickness - 5mm
Rear brake pad thickness - 3mm

Subtotal	\$765.45
GST	\$76.55
Total	\$842.00
Paid	\$842.00
Balance Due	\$0.00

Thank you for your business, if you are happy with the service that you have received please be so kind as to leave a review on our Google or Facebook page. If you have any questions or concerns please do not hesitate to call. Stuart, Rob, and the team look forward to seeing you next time.

BANK DETAILS:
Bank: Commonwealth Bank
BSB: 064-159
Account No: 1046 1556
Account Name: Premium Automotive (QLD) Pty Ltd
REFERENCE: PLEASE USE YOUR INVOICE NUMBER AS YOUR REFERENCE

We acknowledge and pay respect to the land and the traditional custodians of the Kabi Kabi and the Jinibara peoples of eastern Queensland, Australia. The lands on which our business is located and where we meet, work, and learn.

We acknowledge the traditional owners of this land whose cultures and customs have nurtured and continue to nurture this land.

We pay respects to the elders past and present.