Canberra Toyota

SERVICE TAX INVOICE

Eagers TACT Pty Ltd t/as Canberra Toyota T 02 6222 1904

44 Wollongong Street, Fyshwick, ACT 2609 PO Box 1142, Fyshwick ACT 2609

fy shwick. service @can be rrato yota.com.

canberratoyota.com.au

ABN: 43 658 497 299 ACN: 658 497 299 MDI: 20000578

REPAIR ORDER No: PAGE: R064125471 1

PIDE. 20000376				C1 Cu	stomer (Cash)	
	CUSTOMER:		DATE:	TIME IN:	TIME OUT:	KILOMETERS:	ADVISER:
	IBE PTY LTD		22/11/2023	9:30 AM	3:15 PM	123395 MONTHA	GTU
	nbo street ABUNDAH ACT	2604	Yaris Cross H		Auto CVT		
NARRA	ABUNDAH ACI	2004	REG. No:	STOCK No:	T	SELLING DEALER:	
			YQV30G	024568			
	CUSTOMER No:		VIN:			ENGINE No:	
	110465	JIDKCA	AC360L001499			M15AY111701	
1	CONTACT NAME: MR REMI NOUBEL			COLOUR/TRIM I Pearl/Grey	Fahric	ORDER	K No:
	CONTACT NUMBERS:	e las in the	WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date:
M:0431715940					01/02/2031	200000	31/03/2021
				PRICE	QTY	Y/HRS	AMOUNT
JOB DETAILS							
		km service as per ha				2.9	406.00
	ut 96 months/120,00 Replaced engine of	0km service as per h	nandbook.				
Inspected	engine coolant.	a on miter.					
	inverter coolant.	uding radiator & boso	ne.				
Inspected	radiator & condens	uding radiator & hose er for debris & signs	of damage.				
Inspected	battery electrolyte, air filter element.	cleanliness & security					
	brake fluid.						
Replaced	fuel filter.	ur control valvo 8 fue	al lines				
Inspected	charcoal canister.	ur control valve & fue	ei iiiles.				
Inspected	brake pads & discs	S.					
Inspected	brake pipes & hose exhaust system for	s. signs of wear or dar	mage.				
Inspected	steering wheel, gea	ır & linkages.					
	drive shaft boots. drive shaft bolts.						
Inspected	ball joints & dust of	overs.					
Inspected Inspected	front & rear susper towbar (if fitted).	ision.					
Checked	condition & pressure	es of all tyres includir	ng spare.				
Checked Checked	brake pedal height (lights winer/washers	& hand brake lever o , horn & electrical sy	peration. stems.				
Inspected	driver's floor mat for	or correct fitment and	retention.				
Inspected Replaced	all seat belts opera air conditioning fres	ition and condition. h air filter					
Cleaned I	IV battery cooling in	ntake filter.					
	hybrid health checl vice reminder.	K .					
Road test	ed vehicle & reporte	ed any defects.					
TYRES:	FRONT 4MM	REAR 3MM					
BRAKES:		REAR 6MM					
PRT 08888000	01C W/SCR	EEN WASH 1				1	.90
PRT 72693120	во ноок	RR SEAT				2	11.68
PRT 77024523	30 PLATE	SUB-ASSY FUEL				1	232.79
		*****	CONTINUED	******			
CASH				JOBS & NO	TES EXPLA	INED	
	DEE						
CREDIT CARD	REF			COSTS EXF		W EVE: ****	
EFTPOS	REF					TY EXPLAINED)
OTHER (DETAIL	S)		DA	TE: /	/	TIME:	

DELIVERED BY	 RECEIVED BY	

Canberra Toyota

SERVICE TAX INVOICE

gers TACT Pty Ltd t/as Canberra Toyota
Wollongong Street,
ryshwick, ACT 2609
PO Box 1142, Fyshwick ACT 2609

fyshwick.service
au

fy shwick. service @can be rrato yota. com.

canberratoyota.com.au

ABN: 43 658 497 299 ACN: 658 497 299

DELIVERED BY

MDL: 20000578

REPAIR ORDER No: PAGE: R064125471 2

						CT Cus	stomer (C	asn)			
	-										
		STOMER:		DATE: 22/11/202	2	9:30 AM	3:15 PM		ETERS: 23395	ADVIS	SER: STU
	LANOUBE			22/11/202	.5	VEHICLE:	3.15 PW	- 1	MONTHAY		AIR:
	3 Anembo NARRABU		2604	Yaris Cros	s Hy		Auto CVT F	latch	01/20		AIR:
	NANNABO	NDAH ACI	2004	REG. No:	1	STOCK No:	T		G DEALER:		
				YQV30G		024568					
		CUSTOMER No:		VIN:				NGINE			
		110465	JTDKO	CAC360L0014			N	115A	/111701		
		NTACT NAME: REMI NOUBEL		٠,		colour/trim Pearl/Grey I	Eabria		ORDER	No:	
	IVIT	CONTACT NUMBERS:		WAR. E		WAR. KM:	EXT.WAR.EXP:		.WAR.KM:	PD	R Date:
M:043171	5940	CONTACT NUMBERO.		"^	ΑΓ.	WAN. NW.	01/02/2031		200000		3/2021
JOB DET	TAILS					PRICE	QTY/	HRS		AM	OUNT
PRT	7716947030	GASKE	T FUEL SUCTION					1			6.37
PRT	8713928020		NT AIR REFINER					1		4	14.16
PRT	9030107046		O(FOR FUEL PRES	SURE RE				1			4.81
PRT	9030115024	RING C	.33					1			5.15
PRT	9043012031	GASKE						1			2.00
PRT	90915YZZN2		TER 65*72					1		,	21.30
CON		Prof Fuel Saver									53.46
CON	_	Fluid (Dot 3)									16.50
MIS	Environmenta										10.00
MIS	Workshop Su	•									9.50
"""	Workshop 30	indries	IOE	3 1 SUBTO	ΓΛΙ					0.	24.62
			301	3 1 30510	AL					04	24.02
JOB DE1	TAII C										
JOB 2		OTH SIDE MIDE	OR NOT FOLDING	•							
100 2						nd confirm		0			
	using out loa	n Vehicle.	faulty getting stuck	. Can compa	e ai	nd confirm					
	84872-47070	ex syd									
			JOE	2 SUBTO	ΓAL				N	сн	ARGE
JOB DET	TAILS										
JOB 3	SAFE-T-STO	P SAFETY INSPI	ECTION					0			
	Safe-T-Stop S	Safety Inspection									
	•	, , , , , , , , , , , , , , , , , , , ,									
	C-4- T C4										25.00
MIS	Safe-T-Stop				200						35.00
			JOE	3 SUBTO	ΓAL						35.00
l											
JOB DET	TAILS										
			*****	CONTINUE	D ·	*****					
CASH	No.			JOHNHOL	_						
CASH						JOBS & NO	OTES EXPLAI	NED			
CRED	OIT CARD	REF				COSTS EXF	PLAINED				
EFTP	os	REF			$\overline{\Box}$	FLOOR MA	TS SECURITY	Y EX	PLAINED		
OTHE	R (DETAILS)				DA	TE: /			Æ:		
-	()						-	- 30			

RECEIVED BY



TRACTION BATTERY HEALTH CHECK


Guest Name / Company name

VIN Number JTMBW3FV10D075889


Model RAV4 Hybrid (AXAH52R & AX Rego


KM's 105257

Date Checked 11/08/2023











Internal Resistance			Voltage Variation			\bigcirc	
Block	Ref. Value	Meas. Value	Result	Block	Ref. Value	Meas. Value	Result
Block 1	0.010 to $0.100~\Omega$	0.023	\oslash	Block 1	12.00 to 20.00 V	15.43	\bigcirc
Block 2	0.010 to $0.100~\Omega$	0.022	\odot	Block 2	12.00 to 20.00 V	15.40	\bigcirc
Block 3	0.016 to 0.200Ω	0.022	\oslash	Block 3	24.00 to 40.00 V	30.78	\bigcirc
Block 4	0.016 to $0.200\ \Omega$	0.022	\bigcirc	Block 4	24.00 to 40.00 V	30.73	\bigcirc
Block 5	0.016 to $0.200~\Omega$	0.022	\bigcirc	Block 5	24.00 to 40.00 V	30.78	\bigcirc
Block 6	0.016 to $0.200~\Omega$	0.022	0000000000	Block 6	24.00 to 40.00 V	30.78	0000000000000
Block 7	0.016 to $0.200~\Omega$	0.022	\bigcirc	Block 7	24.00 to 40.00 V	30.83	\bigcirc
Block 8	0.010 to $0.200~\Omega$	0.023	\bigcirc	Block 8	24.00 to 40.00 V	30.83	\bigcirc
Block 9	0.010 to $0.100~\Omega$	0.023	\bigcirc	Block 9	12.00 to 20.00 V	15.40	\bigcirc
llock 10	0.010 to 0.100 Ω	0.023	\oslash	Block 10	12.00 to 20.00 V	15.45	\bigcirc
Block 11	0.010 to $0.100~\Omega$	0.024	\bigcirc	Block 11	12.00 to 20.00 V	15.48	\bigcirc
lock 12				Block 12			
lock 13				Block 13			
lock 14				Block 14			
lock 15				Block 15			
lock 16				Block 16			
ock 17				Block 17			
ock 18				Block 18			
ock 19				Block 19			
ock 20				Block 20			







Optimal tyre wear

+
Better fuel economy

DRAG -ALIGNMENT TEST REPORT



= PASS = FAIL = INSPECTION RECOMMENDED

Vehicle No: Examiner No: Station No: Calibration Due: Serial No:

54/ A53233 Apr 2024 PU1110411

Canberra Toyota 44 Wollongong Street Fyshwick ACT 2609 Australia

Signature



22.11.2023 09.39.05