

# Barry Cooper Auto Repairs

82 Federal Street  
North Hobart TAS 7000

ABN 88 009 542 376  
Tel: 03 6234 2243 Fax: 03 6234 2482  
Email: bcar@eftel.net.au  
Website: www.repcoservice.com  
After hours 0418882043



## Tax Invoice

**Invoice No.** 35741      **Date** 3/4/2024      **Sales ID** Hurd. Zack

### Client details

Weining Li  
33 Cribb AVE  
Mitchelton 4053

### Vehicule Details

**Registration** C15JV      **ODO** 240880  
**Make/Model:** Peugeot 4007  
**Year** 2011

### JOB DETAILS

Carry out 240,000km service as per handbook  
Includes Replaced engine oil & oil filter  
Inspected drive belt  
Inspected batteryelectrolyte, cleanliness & security  
Inspected brake fluid  
Checked power steering fluid  
Checked condition & pressures of all tyresincluding spare.  
Checked lights, wiper/washers, horn, lights & electrical systems  
Inspected all seat belts operation & condition  
Road tested vehicule & reported any defects.

### PARTS

Gasket	1	\$1.95
Oil filter	1	\$30.15

### Consumables

Engine oil 5W-30		\$75.00
	Labor	\$88.40
	Miscellaneous	\$20.00

Notes:

<b>Subtotal</b>	<b>\$215.50</b>
<b>GST</b>	<b>\$21.55</b>
<b>Total</b>	<b>\$237.05</b>