



88 Parramatta Road
Croydon New South Wales 2132
ABN: 18 641 497 636
Licence: MVRL58400
 AU54955
Tel: 02 9744 5664
Email: conrad@innerwestauto.com.au
Website: http://www.innerwestauto.com.au

BILL TO:

Moritz [REDACTED]
 [REDACTED]
 [REDACTED]
 [REDACTED]
 [REDACTED]

[REDACTED]
 [REDACTED]
Date: 05/04/2024
Due Date: 05/04/2024

FOR:

Service & Rego
Odometer: 226,667 Kms

Model: Toyota Corolla
Reg No: YWY615
Next Service Date: 08/10/2024
Next Service Odometer: 236,667 Kms
VIN: JTDER23E900062768
Year: 2002

Description	Qty.	Unit Price	Amount
Road Worthy			
Safety Check (Pink Slip)	1.0	\$41.82	\$41.82
Service			
Evolution 10W40 Semi Syn	4.5	\$16.50	\$74.25
Oil Filter	1.0	\$22.00	\$22.00
Sump Plug Washer	1.0	\$3.00	\$3.00
Windscreen Washer Additive	1.0	\$4.00	\$4.00
Environmental Levy	1.0	\$6.82	\$6.82
Workshop Materials Used	1.0	\$15.50	\$15.50
6MM Wiper Blade	1.0	\$12.00	\$12.00
Front Sway Bar Link	2.0	\$81.88	\$163.76
Brake Fluid DOT4	1.0	\$18.00	\$18.00
Labour			\$390.00
Rounding to 5c	1.0	-\$0.01	-\$0.01

Carry out Service.
Perform engine oil and filter change. Replace sump plug washer.
Grease all driveline joints and ball joints (If applicable).
Perform full exterior light check.
Check operation and condition of all wipers.
Check operation of A/C and heating.
Test battery and correct fluid levels if applicable.
Check and correct all under bonnet fluid levels.
Lubricate door, bonnet, boot hinges and locks if necessary.
Check condition of drive belt(s) and timing belt if applicable.
Check operation of handbrake.
Check condition, tread depth, wear & age of all tyres.
Check and correct all tyre pressures including spare.
Remove under trays and inspect under body for fluid leaks.
Check condition of all brake components.
Front brakes: 80% Remaining. Rear brakes: 80% Remaining.
Check steering and suspension components for wear and play.
Clear debris and leaf litter from top of plenum.
Reset service light if applicable.

Minor engine oil leak from timing case area.
Degrease engine and road test vehicle. Recheck for leaks and find none.

Rear wiper requires replacement.
Remove and replace rear wiper.

Brake fluid due for replacement and moisture content excessive.
Drain and clean brake fluid reservoir. Connect brake bleeding equipment.
Raise vehicle on hoist, perform full flush of brake fluid from all brake calipers and/or wheel cylinders and bleed air from system. Bleed hydraulic clutch system if applicable.
Correct fluid level and check brake pedal feel.

Front sway bar link ball joint boots split and require replacement.
Remove and replace front sway bar links.

Carry out registrations safety check.

Subtotal	██████████
GST	██████████
Total	██████████
Paid B. Transfer	██████████
Balance Due	\$0.00

Thank you for your business.

████████████████████
Name: Inner West Automotive
████████████████████
████████████████████