



Tax Invoice

Date: 06/10/2023
Invoice #: 13648

Triple H Automotive Pty Ltd
Unit 1/ 50 Richland Ave

Phone 0721069169 **Mob** 0490555119
Email info.triplehautomotive@gmail.com

Coopers Plains, QLD 4108

A.B.N. 45621898182

Andres Cardenas
QLD 4123

0415969417

Registration 680GL3
Make/Model TOYOTA HIACE
Odometer 151941
Colour WHITE
VIN 6ZZDKDH2010120372
Next Srvc 06/04/2024
Build Date 2013

Item	Description	Quantity	Unit Price	GST	Total
LABOUR					
	Diesel Engine Service - 150,000km	1.00	\$217.27	\$21.73	\$239.00
	Mechanical Repair Labour - Water Pump Replacement	4.00	\$100.00	\$40.00	\$440.00
Labour Total					\$679.00
PARTS					
	Sump Plug Washer /O-Ring	1.00	\$0.00	\$0.00	\$0.00
	Penrite Enviro+ C2 0W-30 Engine Oil 1L	6.80	\$0.00	\$0.00	\$0.00
	Oil Filter	1.00	\$0.00	\$0.00	\$0.00
	Car Wash In and Out - Complimentary	1.00	\$0.00	\$0.00	\$0.00
	AIR FILTER A1632 TOYOTA TOYOTA	1.00	\$68.18	\$6.82	\$75.00
	Cabin Filter (RCA164MS/RCA178MS)	1.00	\$50.00	\$5.00	\$55.00
	WATER PUMP HIACE KDH Dsl '05-	1.00	\$231.82	\$23.18	\$255.00
	Penrite 8 Year 500,000km Red Coolant	5.00	\$10.00	\$5.00	\$55.00
Parts Total					\$440.00
				Subtotal	\$1017.27
				GST	\$101.73
				Total	\$1119.00
Balance Due					\$0.00
Paid Cash					\$1119.00

Invoice Notes

Please Book For Recheck After 1 Week

- **Alternator Charging Low - 13.5V - Customer Noticed**
- Auto Transmission Fluid Dirty and Minor Leaking From Pan
- Front Sway Bar Link Bushes Cracked - Minor
- All Disc Rotors Uneven, Pad OK
- Timing Belt Has Been Replaced @ 100,000km