## **AutoKeepers®**

BILL TO: Juzef Tel: 0412115295 Email: jozef93@hotmail.it 12 Ferry Road West End Queensland 4101 ABN: 20 925 549 298 Tel: (07) 38442645 Email: westend@autokeepers.com.au Website: https://www.autokeepers.com.au/

## TAX INVOICE

Tax Invoice Number: 3519 Date: 15/12/2023 Due Date: 15/12/2023

## FOR:

AutoKeepers Keeping It Right Service Package, Brake fluid system flush, Replace Air Filter, Replace Rocker Cover Gasket **Odometer:** 288,669 Kms Model: Toyota Corolla Reg No: MAS10 Next Service Date: 14/06/2024 Next Service Odometer: 298,669 Kms

Description	Qty.	Unit Price	GST	Amount
AutoKeepers Keeping It Right Service Package				
Keeping it right service -	1.0	\$179.00	\$16.27	\$179.00
Inspect and inflate tyres	1.0	\$0.00	\$0.00	\$0.00
Valvoline engine oil up to 7 liters	1.0	\$0.00	\$0.00	\$0.00
Oil filter replacement	1.0	\$0.00	\$0.00	\$0.00
Top up all under bonnet fluid levels	1.0	\$0.00	\$0.00	\$0.00
Roadtest and handling check	1.0	\$0.00	\$0.00	\$0.00
127 point check and report	1.0	\$0.00	\$0.00	\$0.00
Vehicle consultation	1.0	\$0.00	\$0.00	\$0.00
Replace service sticker	1.0	\$0.00	\$0.00	\$0.00
Stamp and date log book	1.0	\$0.00	\$0.00	\$0.00
Replace Air Filter				
Supply New Air Filter	1.0	\$69.00	\$6.27	\$69.00
LAB - Labour	0.2	\$160.00	\$2.91	\$32.00
Brake fluid system flush				
Brake system fluid flush -	1.0	\$109.50	\$9.95	\$109.50
Raise car on hoist	1.0	\$0.00	\$0.00	\$0.00
Remove all vehicles wheels	1.0	\$0.00	\$0.00	\$0.00
Suck old brake fluid out of reservoir	1.0	\$0.00	\$0.00	\$0.00
Fill reservoir with new brake fluid	1.0	\$0.00	\$0.00	\$0.00
Attach sucker to each wheel and crack bleed nipple at each wheel in order	1.0	\$0.00	\$0.00	\$0.00

Once clean fluid comes through each caliper close nipple	1.0	\$0.00	\$0.00	\$0.00
Top up level in reservoir once complete	1.0	\$0.00	\$0.00	\$0.00
Refit wheels and road-test	1.0	\$0.00	\$0.00	\$0.00
Replace Rocker Cover Gasket				
Remove the Intake	1.0	\$0.00	\$0.00	\$0.00
Remove Solenoid	1.0	\$0.00	\$0.00	\$0.00
Remove Spark Plug Wires Etc	1.0	\$0.00	\$0.00	\$0.00
Remove Valve Cover Bolts and Remove the Valve Cover	1.0	\$0.00	\$0.00	\$0.00
Optional - Suck Out Any Oil	1.0	\$0.00	\$0.00	\$0.00
Clean the Mating Surfaces	1.0	\$0.00	\$0.00	\$0.00
Apply the RTV Gasket Material	1.0	\$0.00	\$0.00	\$0.00
Put the Valve Cover Back On	1.0	\$0.00	\$0.00	\$0.00
Final Steps and checks	1.0	\$0.00	\$0.00	\$0.00
Supply new gasket	1.0	\$76.50	\$6.95	\$76.50
Labour - Labour to Install All Components	0.75	\$176.00	\$12.00	\$132.00

Subtotal	\$543.64
GST	\$54.36
Total	\$598.00
Paid Eftpos	\$598.00
Balance Due	\$0.00

AutoKeepers is committed to keeping your car safe, reliable and enjoyable by Keeping It Right For You.

Refrigerant Trading Authority: AU54231

I hereby accept re-delivery of the car and approve the above invoiced works as discussed prior to completion.

Customer Signature...... Date....../....../......

Bank Account BSB > 083 321 Account number > 142903707