

From					
Risker Pty Ltd 605/1B George St Mayfield East, NSW 2304			0249069084 Mob 0423679675 newcastleauto@foxmail.com		
	A.B.N.	2861086	28610867957		
To MARTIN MOTORS PTY LTD		Registration Make/Model Odometer VIN	BJ28JE TOYOTA CAMRY 262000		
Item	Description	Quantity	Unit Price	GST	Total
LABOR					
E SAFEYT P/S	E SAFEYT CHECK PINK SLIP	1.00	\$40.00	\$3.64	\$40.00
LAB	Labour	1.20	\$100.00	\$10.91	\$120.00
			I	_abor Total	\$160.00
PARTS					
R1040SN-205	Penrite 10w-40 Synthetic Engine Oil	4.50	\$11.00	\$4.50	\$49.50
C-1124	Z432 OIL FILTER	1.00	\$15.45	\$1.40	\$15.45
DRC020	RADIATOR CAP 16PSI 110KPA ME RECOVERY TYPE EXTRA	TAL 1.00	\$15.00	\$1.36	\$15.00
USEDTYRE	Second hand tyre	2.00	\$45.00	\$8.18	\$90.00
ENLY	W aste disposal & Workshop Consumables	1.00	\$15.05	\$1.37	\$15.05
				Parts Total	\$185.00
				Subtotal	\$313.64
				GST	\$31.36
				Total	\$345.00
			В	alance Due	\$345.00

Invoice Notes

Carried out service Replaced front tires Replaced radiator cap Re-clamped FR CV shaft boot and cleaned grease

EFT Account Info:

Risker Pty Ltd BSB 062 815 Acc 1050 4835

RTA : AU53567