



Tax Invoice

19/04/2024

Job #: 55403

License #: MVRL43713

MotorServe Port Melbourne	Phone 0390608098
250A Ingles Street	Email portmelbourne@motorserve.com.au
Port Melbourne, VIC 3207	Web
	A.B.N. 41 121 715 393
	Fax

Sabrina Young	Registration DJB27A
MOOREHOUSE CRES	Make HOLDEN
EDENSOR PARK, NSW 2176	Model CRUZE
	Colour RED
	Odometer 116558
0466039662	VIN 6G1PD5EM9GL241572

Description	RRP	Qty	Total
-------------	-----	-----	-------

Coolant 5.0L	\$0.00	1.00	\$0.00
		Total:	\$0.00

Replace Water Pump

Removed all necessary components to gain access
 Removed and replaced water pump assembly
 Supplied and fitted new hose clamps as required
 Re-fit all previously removed components

Labour			\$289.40
		Total:	\$289.40

Labor required for this service in total 5.0

Labour			\$835.00
		Total:	\$835.00

Cooling System Flush

Carried out cooling system drain and flush
 Re-filled cooling system with specified engine coolant
 Bleed all air from cooling system and inspected to ensure there are no leaks

Labour			\$83.50
		Total:	\$83.50

Replace Rocker Cover Gasket

Rectified engine oil leak from rocker cover gasket
 Removed engine rocker cover and replaced gasket as required
 Reassembled and cleaned area, road tested and checked, All ok at time of testing

Labour			\$86.90
		Total:	\$86.90

Labour

Labour			\$0.00
		Total:	\$0.00

10% off for RACV Members

RACV members receive 10% off their invoice,
 displayed in discount field below

Labour			\$0.00
		Total:	\$0.00

Subtotal Inc. GST:	\$1294.80
Discount:	\$165.00
Total Due Inc. GST:	\$1129.80
GST:	\$102.71
Balance Due	\$1129.80

Invoice Notes

Technician's Notes:

The rocker cover gasket was replaced due to being twisted, which caused an oil leak. Following the replacement, thorough inspections confirm that there are currently no oil leaks detected.

Suggested Repairs:

Major: Requires immediate attention / safety concern

- There are no major repairs listed in the provided information.

Moderate: Requires attention before your next service

- Engine Air Filter
- Power Steering Fluid Flush

Minor: Monitor / reinspect at your next service

- Disc Brake Rotor
- Brake Pads Set

Account Customer Banking Details
Bank Name: National Australia Bank (NAB)
Account Name: Motorserve
BSB Number: 082 057
Bank Account Number: 30067 9449

Standard Motorserve terms and conditions apply, available at motorserve.com.au/terms-and-conditions. Motorserve Pty Ltd. ABN 41121715393 trading as Motorserve, NSW license number MVRL43713 and ACT license number 20000142 is an entity within the IAG group. Need more information? Visit motorserve.com.au