UberCarshare

INSPECTOR NAME

Owner's Service Form

DATE OF INSPECTION

Inspection		Pass	Fail	Insp	ection		Pass	Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake	$\bigcirc \ \ \ \ \ \ \ \ \ \ $	0 0 0 0 0	7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights		$\bigcirc \ \ \ \ \ \ \ \ \ \ \ \ $	0 0 0
				8	DOORS (open, close, I	ock)	\bigcirc	0
2	CLUTCH (manual only)	0	0	9	SPEEDOMETER		\bigcirc	0
3	TYRES Right front Right rear Left front Left rear		0 0 0	10 11 12	WARNING LIGHTS REAR VIEW MIRRORS SEAT BELTS		⊗⊗	0
4	STEERING	\bigcirc	0	13	AIRBAGS		\bigcirc	0
5	SUSPENSION Front Rear	& & O	0 0					
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available		000000	m	This car was inspected by the qualified mechanic listed below and satisfactorily basses the checks listed on this form. PASS FAIL			
1YN5RA Honda				Hiad	ce	2008		
CAR REGO CAR MAKE				CAR N	MODEL	CAR YEAR		
LMS Auto Care						170291		
INSPECTION COMPANY NAME						ODO MILEAGE		
Sameera Hadigallage						_04/092023	3	

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

INSPECTOR SIGNATURE