

ANZ CUSTOMER COPY

Date: 04/08/2023
Invoice #: 54585

HAYNE & STAGG P/L

121 MELVILLE ST
HOBART TAS 7000

TERMINAL ID 05787019101
MASTERCARD (C) CR
9063

PUR AUD \$143.00

Debit Mastercard

AID A0000000041010

TUR 0000048001

APSN 04 P00002 ATC 002F

APPROVED AUTH 610570

STAN 011113

04/08/23 16:57

THANK YOU
FOR YOUR CUSTOM
PLEASE RETAIN FOR YOUR RECORD

Phone 0362313444 **Mob** 0428958744
Email service@jpautomotive.net.au
Web www.jpautomotive.com.au
A.B.N. 79630050056

Registration J10JF
Make/Model Nissan ENV200
Odometer 45424
Colour White
VIN 6U900000ME0508933
Build Date 5/2015

Item	Description	Quantity	Unit Price	GST	Total
LABOUR					
ELECTRIC VEHICLE CHECK		1.00	\$130.00	\$13.00	\$143.00
	<i>Check exterior/interior lights, wipers, horn, demister, seats and seat belts. Checked doors, windows, boot and bonnet mountings. Connect diagnostic scan tool to check for faults in control systems. Checked battery hold down. Checked engine and gearbox mountings. Raise vehicle and checked suspension, brakes, steering, wheels, bearings and tyres. Road test vehicle</i>				
				Labour Total	\$143.00
				Subtotal	\$130.00
				GST	\$13.00
				Total	\$143.00
				Balance Due	\$143.00

Thank you for trusting JP Automotive with your vehicle.
We take great pride in our workmanship and professionalism.
Safe Motoring.

Note that our Banking details are:
Account Name - Hayne and Stagg | BSB - 017-010 | Account Number - 420264723

Approved Inspection Station
Vehicle Inspection Checklist
Light Motor Vehicle



Hobart
Vehicle Examiner 1730
D. Barber
Inspection Date: 04/08/23

VEHICLE DETAILS

Make: Nissan Model: Env200 Type: Van Year of compliance/manufacture: 01/15 Colour: white
Odometer: 45,424 GVM: - GCM: - Fuel Type: Electric No of cylinders: 0
Manufactured seating: 7 Seating capacity: 7

VIN/Chassis No

6	U	9	0	0	0	0	M	E	0	5	0	8	9	3	3
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Engine No EM57 087850A Approval Number 1050509/023

- 1. IDENTITY**
 - Compliance Plate
 - RAV Entry
 - VIN/Chassis No
 - Engine No
 - 2nd stage manufacture plate
 - Modification plate
 - Previous Registration History
- 2. ELECTRICAL**
 - Headlight/park lights
 - Headlight alignment
 - Tail lights
 - Indicators
 - Brake lights (including eyelevel)
 - Reverse lights
 - Reflectors
 - Lens condition
 - Windscreen wipers/washers
 - Horn
- 3. INSIDE CHECKS**
 - Heater/demister
 - Heater fan
 - ABS/SRS lights
 - Pedal condition/height
 - Handbrake operation
 - Inhibitor switch (automatic)
 - Steering wheel/freeplay
 - Door operation
- 4. MIRRORS**
 - Condition/mountings
- 5. SEATS**
 - Condition/mountings
 - Adjustments
- 6. SEAT BELTS**
 - Condition/mountings
 - Compliance
 - Locking/snatch test
- 7. BODY CHECK**
 - Rust
 - Protrusions
 - Bonnet safety catch
 - Windows
 - Windows glazing/tinting:

	%
--	---

 Factory Y N
 - Security of all external attachments
- 8. UNDER BONNET CHECK**
 - Master cylinder
 - Engine oil leaks
 - Engine fuel leaks
 - Air cleaner
 - Engine mountings
 - Exhaust system
 - Battery security
 - Wiring security
 - Steering shaft/coupling
 - Power steering leaks
- 9. STEERING**
 - Steering box/rack
 - Linkages/joints
 - Tie rod ends
 - Idler arm
- 10. FRONT SUSPENSION**
 - Control arms
 - Bushes
 - Ball joints
 - Spring/shock absorbers
 - Bump stops
 - Modifications *

L	mm
R	mm
 - *Suspension height

	mm
--	----
- 11. WHEELS & TYRES FRONT**
 - Condition
 - Tread pattern
 - Tyre speed/load rating
 - Rims/mountings
 - After market tyres/rims *

	mm
--	----
 - *Wheel track

	mm
--	----
- 12. BRAKES**
 - Pipes and hoses
 - Discs and drums
 - Fluid leaks
 - Caliper/hose security
 - Pads and linings
 - Linkages
 - Park Brake
- 13. ENGINE & DRIVELINE**
 - Mountings
 - Oil/fluid leaks
 - Universal joints
 - Centre bearing
- 14. EXHAUST**
 - Exhaust leaks
 - Clearance - hoses/wiring
 - Catalytic converter
- 15. REAR SUSPENSION**
 - Control arms
 - Bushes
 - Ball joints
 - Springs/shock absorbers
 - Bump stops
 - Modifications*

L	mm
R	mm
 - * Suspension height

	mm
--	----
- 16. WHEELS & TYRES REAR**
 - Condition
 - Tread pattern
 - Tyre speed/load rating
 - Rims/mountings
 - After market tyres/rims*

	mm
--	----
 - *Wheel track

	mm
--	----
- 17. FUEL TANK**
 - Mountings/condition
 - Fuel lines
 - Fuel leaks
- 18. LPG GAS**
 - Gas compliance (certificate in date)
- 19. UNDER BODY & FRAME**
 - Rust
 - Cracks
 - Bends/kinks
 - Modifications/repairs
 - Mudguards/mudflaps
- 20. MOTORHOME**
 - Gas compliance
 - Compliant fire extinguisher
 - Door mounted on LHS or rear

Comments Hire & Drive Passenger Service Inspection Pass Fail N/A