


# SERVICE TAX INVOICE



HOBART DEALERSHIP PT.  
235 ARGYLE ST  
HOBART TAS 7000

artkia.com.au

3 049 LMCT: 6056

REPAIR ORDER No: JCB0043639	PAGE: 1
C1 Customer (Cash)	

TID P3647737  
MID 04426581  
DATE/TIME 27/03/24 17:19

RRN 271719027394  
STAN 027394 AUTH 143213  
CARD .....7537 SAV(T)  
DEBIT PSN 01  
eftpos SAV  
AID A00000038410  
TVR 0000048000 ATC 0051  
ARQC 887987FA46032B02

PURCHASE AUD 607.00

APPROVED 0000

CUSTOMER COPY

DATE: 27/03/2024	TIME IN: 7:50 AM	TIME OUT: 5:00 PM	KILOMETRES: 61331	ADVISER: KO
VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety f			MONTH/YEAR 06/2021	AIR:
REG. No: J25TY	STOCK No: US02034	SELLING DEALER:		
OMER No: 48	VIN: KNAF251CMN5115553	ENGINE No: G4NAMH504725		
NAME: Iain Mckean	COLOUR/TRIM: Clear White (UD)/Graphite/Saturn Black (WK)	ORDER No:		
ACT NUMBERS:	WAR. EXP: 02/07/2028	WAR. KM: 999999	EXT.WAR.EXP: 01/01/2033	EXT.WAR.KM: 175000
				RDR Date: 02/07/2021

		PRICE	QTY/HRS	AMOUNT
<b>JOB DETAILS</b>				270.22
JOB 1	Carry out 60,000km/48 month Kia Capped Price Servicing (MYR)2021 to 2021 Carried out 60,000km/48 month Kia Capped Price Servicing. Added Genuine Oil System Cleaner Replaced Engine Oil with 5W/30 A5 Replaced Oil Filter with Genuine Filter Replaced Sump Plug Washer with Genuine Washer Added Genuine Fuel Additive Replaced Brake Fluid with Genuine Brake fluid Replaced Cabin Pollen Filter with Genuine Filter Replaced Fuel Tank Air Filter with Genuine Filter Inspected Engine Air Filter Inspected Cooling System Inspected Drive Belts Inspected Vacuum and Crankcase Ventilation Hoses Inspected Fuel lines & hoses Inspected Exhaust System Visually Inspected Battery Condition Inspected Brake Lines, Hoses etc Inspected Park Brake and adjusted where necessary Inspected Disc Brakes and Disc Pad Condition, registered all measurements Inspected Power Steering System (For MDPS, inspected Steering Rack etc.) Inspected Tyres (pressure & tread) Inspected Driveshaft Boots Inspected Front & Rear Suspension Inspected A/C Compressor Inspected Air Conditioner Refrigerant Inspected Vapour Hose, Fuel and Filler Cap Inspected Valve Clearance (Audible Only) Checked for Outstanding Service Campaigns and Recalls Connected Kia Diagnostic System (KDS) and check for DTC's Kia Roadside Assistance Activated Performed Quality Control Road Test after completing service Topped up Windscreen Washer fluid with Genuine windscreen washer fluid Carried out Kia Vehicle Inspection Checklist			
PRT	2151323001 GASKET-ENGINE OIL PAN DRAIN		1	1.39
PRT	2630035505 FILTER ASSY-ENGINE OIL		1	9.45
PRT	31453M6100 VALVE-CANISTER CLOSE		1	75.96
PRT	3426889 KIA BRAKE FLUID 500ML DOT4		2	20.20
***** CONTINUED *****				

CASH   
  MASTERCARD   
  VISA CARD   
  EFTPOS   
 Payment Received with Thanks on the \_\_\_\_/\_\_\_\_/\_\_\_\_

# SERVICE TAX INVOICE

et, Hobart TAS 7000  
 370 E: service@hobartkia.com.au  
 ia.com.au  
 7 035 787 ACN: 631 123 049 LMCT: 6056  
 Pty Ltd T/A Hobart Kia

REPAIR ORDER No: JCB0043639	PAGE: 2
C1 Customer (Cash)	

CUSTOMER: <b>BENJAMIN JAMES MCKEAN</b> 23 Salacia Ave HOWRAH TAS 7018	DATE: 27/03/2024	TIME IN: 7:50 AM	TIME OUT: 5:00 PM	KILOMETRES: 61331	ADVISER: KO
	VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety F			MONTH/YEAR 06/2021	AIR:
	REG. No: J25TY	STOCK No: US02034	SELLING DEALER:		
	VIN: KNAF251CMN5115553			ENGINE No: G4NAMH504725	
CUSTOMER No: 31848	CONTACT NAME: Mr Benjamin Mckean			ORDER No:	
CONTACT NUMBERS: M:0437507047			COLOUR/TRIM: Clear White (UD)/Graphite/Saturn Black (WK)		RDR Date: 02/07/2021
WAR. EXP: 02/07/2028		WAR. KM: 999999	EXT. WAR. EXP: 01/01/2033	EXT. WAR. KM: 175000	

JOB DETAILS	PRICE	QTY/HR	AMOUNT
PRT 97133F2000 FILTER ASSY-AIR		1	51.61
PRT AK0C0WS005 WINDSCREEN WASHER SOLUTION		1	2.68
PRT C0A39APK00 OIL SYSTEM CLEANER		1	10.00
PRT KMF300 INJECTOR CLEANER-250ML		1	8.59
CON High Quality 5W-30			60.12
MIS Enviro Waste Recovery KIA			10.00
MIS Shop Supplies KIA			15.00
MIS ROADSIDE ASSIST LEVY			16.60
<b>JOB 1 SUBTOTAL</b>			<b>551.82</b>

**JOB DETAILS**  
 JOB 3 CUSTOMER STATES VEHICLE VIBRATES GOING OVER 100KM  
 Technicians have inspected the guest concern and have informed that the vehicle is shakin gdue to the condition of the tyres. Upon inspection we have found that the tyres all have the wire exposed and requir replacement ASAP.  
**JOB 3 SUBTOTAL** NO CHARGE

**JOB DETAILS**  
 JOB 6 NO SERVICE BOOK  
**JOB 6 SUBTOTAL** NO CHARGE

**RECOMMENDATIONS**  
 27/03/24  
 Technicians have advised of the following:  
 4x new tyres and

\*\*\*\* Next service due: 27/03/2025 or odometer reading: 75000 whichever comes first.

LABOUR	\$270.22
OILS	\$60.12

\*\*\*\*\* CONTINUED \*\*\*\*\*

CASH   
  MASTERCARD   
  VISA CARD   
  EFTPOS   
 Payment Received with Thanks on the \_\_\_/\_\_\_/\_\_\_

# SERVICE TAX INVOICE

Hobart TAS 7000  
 service@hobartkia.com.au

ACN: 631 123 049 LMCT: 6056  
 Hobart Kia

REPAIR ORDER No: JCB0043639	PAGE: 3
C1 Customer (Cash)	

CUSTOMER: <b>BENJAMIN MCKEAN</b> e TAS 7018	DATE: 27/03/2024	TIME IN: 7:50 AM	TIME OUT: 5:00 PM	KILOMETRES: 61331	ADVISER: KO
	VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety f			MONTH/YEAR: 06/2021	AIR:
	REG. No: J25TY	STOCK No: US02034	SELLING DEALER:		
CUSTOMER No: 31848	VIN: KNAF251CMN5115553		ENGINE No: G4NAMH504725		
CONTACT NAME: Mr Benjamin Mckean	COLOUR/TRIM: Clear White (UD)/Graphite/Saturn Black (WK)			ORDER No:	
CONTACT NUMBERS:	WAR. EXP: 02/07/2028	WAR. KM: 999999	EXT. WAR. EXP: 01/01/2033	EXT. WAR. KM: 175000	RDR Date: 02/07/2021

DETAILS	PRICE	QTY/HRS	AMOUNT
PARTS			\$179.88
MISCELLANEOUS			\$41.60
SUBTOTAL			\$551.82
GST			\$55.18
TOTAL INCLUDES GST			\$607.00

PRINTED 27/03/24 16:36:37

CASH  
  MASTERCARD  
  VISA CARD  
  EFTPOS  
 Payment Received with Thanks on the \_\_\_\_/\_\_\_\_/\_\_\_\_

If you wish to pay your invoice electronically please use the following account and use your Customer Number as a payment  
 Account Name: Hobart Dealership Pty Ltd  
 BSB: 334-040  
 Account: 555-308-957