



# ALAN MANCE



461 Barkly St Footscray 3012 PO Box 4072 Footscray West 3012  
Web www.alanmancemitsubishi.com.au

**SERVICE DIRECT**    **SERVICE FAX DIRECT**    **SWITCHBOARD**  
03 9133 0550                      03 9396 8051                      03 9396 8000

<b>Service TAX Invoice</b>		Page 1 of 3		Reprint# 1		Doc #: <b>MIMS138082</b>	
Customer No. 54564	Customer Name & Address YURI BONGALOS U 14 296-298 SOMERVILLE RD  KINGSVILLE VIC 3012			Advisor KYLE HALL                      0555	Colour SUNSHINE ORA	Team SERVICE	
Doc. Date 30/08/23				Year / Make / Model 21/MITSUBISHI/ASX BLACK SAM 2WD 2.0L AUTO			Tag No.
Reg. No. 1VD3OX				Model No. XD2B45	Carline ASX		Eng./Trans. /AUT
Stock No. 19801				Chassis No. 0002672755	Kilometres 28998	Prod. Date 19/02/21	Orig. Del. Date 11/02/22
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Credit Card	Selling Dealer V255	Delivery Kms.	Delivery Date 11/02/22	Warr. Exp. Date
	Vehicle ID. JMFXTGA2WMMU010809	Engine No. 4B11 DG6139	Date & Time Promised 30/08/23      05:00pm	Time Received 11:28am	Quote Price	Air Y	Pwr Y
						Turb Y	
Mobile Phone: 0423-923873	Email Address yuribongalos@gmail.com						

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 1                      01MI76305030N04                      Tech(s): 193                      122.21  
30,000km/24mth service {SoldDate: 01/10/2020-, ModelYr: 2021-2021}

**Customer Instructions:**  
Carried out 30,000km/24 month service as per handbook.  
--- Under The Hood ---  
Replaced engine oil and oil filter.  
Checked drive belt and adjusted tension as required.  
Inspected valve clearances (audible check only), adjust if necessary.  
Inspected cooling system, hoses and connections.  
Checked coolant level.  
Checked air cleaner element for clogging and damage.  
Replaced brake fluid.  
Checked battery terminals for cleanliness and security.  
Checked battery electrolyte specific gravity, level and condition using specified tools.  
--- Under The Vehicle ---  
Inspected suspension and steering components for damage/wear.  
Inspected ball joints, seals, bushes and boots.  
Inspected drive shafts including CV boots.  
Inspected CVT transmission for fluid leaks (in case of leakage, check the fluid level).  
Inspected exhaust system for security and leaks.  
Checked under body for damage and condition.  
--- Inside The Vehicle ---  
Checked the free play and operation of the brake pedal, adjust if required.  
Checked seat belts for damage and operation.  
Checked lights, wiper/washers, horn and electrical systems.  
Inspected air conditioning operation.  
Checked and adjusted park brake as required.  
Replaced fresh air/pollen filter.  
--- Outside The Vehicle ---  
Checked wheel alignment (visual inspection for tyre wear).  
Checked condition and pressures of all tyres including spare.  
Inspected brake hoses and pipes for damage, corrosion and leaks.

CASH	CHEQUE	VISA	M/CARD	B/CARD	EFTPOS	AMEX	DINERS	M/PASS	M/CHARGE	F/GOLD	F/ORANGE	STARFLEET
ROAD TESTED				Alan Mance Mitsubishi - Its Service and agents. Please note that, in servicing or repairing your vehicle: a. Any User generated data (such as music, Telephone numbers or saved map data) stored within the vehicle infotainment system computer or other components containing driver preferences may be lost. b. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods. c. Please execute at my cost as soon as you conveniently can the repairs listed hereto, Also any other work considered essential thereto. d. The vehicle its accessories and contents are at my risk entirely wheather theft or loss thereof arises from any want of care on the part of yourself contractors or servants or from any cause whatsoever. Any claim for workmanship is to be raised within seven days after the vehicle is returned to me.								
ORDER NO.	SUBLET REPAIRS											
Non genuine accessories and Parts (NG) Non Genuine Accessories are not covered by Mitsubishi's warranty and may affect the factory build specs and the warranty provided by Mitsubishi for your Mitsubishi vehicle. I consent that I have read and understand the Alan Mance Mitsubishi privacy policy and Mitsubishi's privacy policy. I consent to my Information being provided to Mitsubishi.												
Please tick the box if you wish to receive marketing material from Mitsubishi Motors, Mitsubishi dealers or other Mitsubishi entities. <input type="checkbox"/>												
SIGNATURE OF/FOR OWNER: .....												



# ALAN MANCE



461 Barkly St Footscray 3012 PO Box 4072 Footscray West 3012  
Web www.alanmancemitsubishi.com.au

**SERVICE DIRECT**    **SERVICE FAX DIRECT**    **SWITCHBOARD**  
03 9133 0550                      03 9396 8051                      03 9396 8000

**Service TAX Invoice**                      Page 2 of 3                      Reprint# 1                      Doc #: **MIMS138082**

Customer No. 54564	Customer Name & Address YURI BONGALOS U 14 296-298 SOMERVILLE RD  KINGSVILLE VIC 3012	Advisor KYLE HALL                      0555	Colour SUNSHINE ORA	Team SERVICE				
Doc. Date 30/08/23		Year / Make / Model 21/MITSUBISHI/ASX BLACK SAM 2WD 2.0L AUTO	Tag No.					
Reg. No. 1VD3OX		Model No. XD2B45	Eng./Trans. /AUT					
Stock No. 19801		Chassis No. 0002672755	Kilometres 28998	Prod. Date 19/02/21	Orig. Del. Date 11/02/22			
Purchase Order No.	Driver	Contract No.	Contract Name	Contract Exp. Kms	Exp. Date			
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Credit Card	Selling Dealer V255	Delivery Kms.	Delivery Date 11/02/22	Warr. Exp. Date	
	Vehicle ID. JMFXTGA2WMMU010809	Engine No. 4B11 DG6139	Date & Time Promised 30/08/23                      05:00pm	Time Received 11:28am	Quote Price	Air Y	Pwr Y	Turb

Inspected brake pads and discs.  
Inspected fuel pipes, hoses and connections for leaks.  
--- Final Inspections and Road Test ---  
Inspected the body of the vehicle for any damage.  
Checked vehicle for outstanding recall or service campaigns.  
Checked all electronic control system diagnosis output using manufacturer specified special tools.  
Reset service indicator.  
Road tested vehicle and reported any defects.

**Total - Labour**                      **122.21**

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	MI7803A109	AIR REFRESHER	59.90	59.90
Job# 1	1	MIMD050317	GASKET-14MM	3.20	3.20
Job# 1	1	MIMD360935	OIL FILTER ASSY	19.36	19.36
Job# 1	1	MIAU901551	FLUID,BRAKE &	10.34	10.34
Job# 1	1	MIMZ691137S	WASHER ADDITIVE	1.54	1.54
<b>Total - Parts</b>					<b>94.34</b>

Petrol, Oils, Lubricants and Supplies	Amount
Job# 1                      MOBIL FORMULA S2 5W30	40.25
Job# 1                      SHOP SUPPLIES	15.00
<b>Total - POL</b>	<b>55.25</b>

Miscellaneous	Amount
Job# A                      BC                      DEPOSIT RECIEVED	0.00
Job# 1                      DAWPS                      Diamond Advantage price variance	Warranty
Job# A                      CENTS                      1 & 2 CENT ROUNDING	0.02
<b>Total - Misc</b>	<b>0.02</b>

<input type="checkbox"/> CASH	<input type="checkbox"/> CHEQUE	<input type="checkbox"/> VISA	<input type="checkbox"/> M/CARD	<input type="checkbox"/> B/CARD	<input type="checkbox"/> EFTPOS	<input type="checkbox"/> AMEX	<input type="checkbox"/> DINERS	<input type="checkbox"/> M/PASS	<input type="checkbox"/> M/CHARGE	<input type="checkbox"/> F/GOLD	<input type="checkbox"/> F/ORANGE	<input type="checkbox"/> STARFLEET
ROAD TESTED				Alan Mance Mitsubishi - Its Service and agents. Please note that, in servicing or repairing your vehicle: a. Any User generated data (such as music, Telephone numbers or saved map data) stored within the vehicle infotainment system computer or other components containing driver preferences may be lost. b. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods. c. Please execute at my cost as soon as you conveniently can the repairs listed hereto, Also any other work considered essential thereto. d. The vehicle its accessories and contents are at my risk entirely wheather theft or loss thereof arises from any want of care on the part of yourself contractors or servants or from any cause whatsoever. Any claim for workmanship is to be raised within seven days after the vehicle is returned to me. Please tick the box if you wish to recieve marketing material from Mitsubishi Motors, Mitsubishi dealers or other Mitsubishi entities. <input type="checkbox"/>								
ORDER NO.	SUBLET REPAIRS											
Non genuine accessories and Parts (NG) Non Genuine Accessories are not covered by Mitsubishi's warranty and may affect the factory build specs and the warranty provided by Mitsubishi for your Mitsubishi vehicle. I consent that I have read and understand the Alan Mance Mitsubishi privacy policy and Mitsubishi's privacy policy. I consent to my Information being provided to Mitsubishi.												
SIGNATURE OF/FOR OWNER: .....												



# ALAN MANCE



461 Barkly St Footscray 3012 PO Box 4072 Footscray West 3012  
Web www.alanmancemitsubishi.com.au

**SERVICE DIRECT**    **SERVICE FAX DIRECT**    **SWITCHBOARD**  
03 9133 0550                      03 9396 8051                      03 9396 8000

<b>Service TAX Invoice</b>		Page 3 of 3		Reprint# 1		Doc #: <b>MIMS138082</b>	
Customer No. 54564	Customer Name & Address YURI BONGALOS U 14 296-298 SOMERVILLE RD  KINGSVILLE VIC 3012			Advisor KYLE HALL                      0555	Colour SUNSHINE ORA	Team SERVICE	
Doc. Date 30/08/23				Year / Make / Model 21/MITSUBISHI/ASX BLACK SAM 2WD 2.0L AUTO			Tag No.
Reg. No. 1VD3OX				Model No. XD2B45			Carline ASX
Stock No. 19801				Chassis No. 0002672755	Kilometres 28998	Prod. Date 19/02/21	Orig. Del. Date 11/02/22
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Credit Card	Selling Dealer V255	Delivery Kms.	Delivery Date 11/02/22	Warr. Exp. Date
Vehicle ID. JMFXTGA2WMMU010809		Engine No. 4B11 DG6139		Date & Time Promised 30/08/23                      05:00pm	Time Received 11:28am	Quote Price	Air Y    Pwr Y    Turb

**Comments**

**BRAKES: FRONT 6MM, REAR 7MM  
TYRES: FRONT AND REAR 4MM  
CPS #5284923**

**Recommendations**

CHECK TYRES AT NEXT SERVICE - 4MM

<b>Total Labour</b>	122.21
<b>Total Parts</b>	94.34
<b>Total POL</b>	55.25
<b>Total Sublet</b>	0.00
<b>Total Misc</b>	0.02

<b>Total Tax</b>	27.18
<b>Total Invoice</b>	<b>299.00</b>

**TOTAL INCLUDING GST**

**ALL PARTS WITH PREFIX MI ARE GENUINE PARTS AND ARE COVERED BY THE MANUFACTURE WARRANTY,PARTS WITH NG ARE NOT GENUINE PARTS. RTA AU45312**

CASH	CHEQUE	VISA	M/CARD	B/CARD	EFTPOS	AMEX	DINERS	M/PASS	M/CHARGE	F/GOLD	F/ORANGE	STARFLEET
ROAD TESTED				Alan Mance Mitsubishi - Its Service and agents. Please note that, in servicing or repairing your vehicle: a. Any User generated data (such as music, Telephone numbers or saved map data) stored within the vehicle infotainment system computer or other components containing driver preferences may be lost. b. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods. c. Please execute at my cost as soon as you conveniently can the repairs listed hereto, Also any other work considered essential thereto. d. The vehicle its accessories and contents are at my risk entirely wheather theft or loss thereof arises from any want of care on the part of yourself contractors or servants or from any cause whatsoever. Any claim for workmanship is to be raised within seven days after the vehicle is returned to me.								
ORDER NO.	SUBLET REPAIRS			Please tick the box if you wish to recieve marketing material from Mitsubishi Motors, Mitsubishi dealers or other Mitsubishi entities. <input type="checkbox"/>								
Non genuine accessories and Parts (NG) Non Genuine Accessories are not covered by Mitsubishi's warranty and may affect the factory build specs and the warranty provided by Mitsubishi for your Mitsubishi vehicle.				I consent that I have read and understand the Alan Mance Mitsubishi privacy policy and Mitsubishi's privacy policy. I consent to my Information being provided to Mitsubishi.								
SIGNATURE OF/FOR OWNER: .....												