


| Inspection | Pass | Fail | Inspection | Pass | Fail |
|-----------------------------------|-------------------------------------|--------------------------|------------------------------------|-------------------------------------|--------------------------|
| 1 BRAKES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 7 LIGHTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right front | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Headlights | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right rear | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Turn indicator lights | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Left front | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Brake lights | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Left rear | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Tail lights | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Handbrake | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| 2 CLUTCH (manual only) N/A | <input type="checkbox"/> | <input type="checkbox"/> | 8 DOORS (open, close, lock) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 TYRES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 9 SPEEDOMETER | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right front | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 10 WARNING LIGHTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right rear | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 11 REAR VIEW MIRRORS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Left front | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 12 SEAT BELTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Left rear | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 13 AIRBAGS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4 STEERING | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| 5 SUSPENSION | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Front | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Rear | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| 6 WINDSCREEN | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Large crack (+3cm)= Fail | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Small crack (-3cm)= Pass | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Front glass | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Front wipers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Rear glass | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Rear wiper (if available) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |

This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.

PASS **FAIL**

| | | | |
|-------------------------|---|----------------|--------------------|
| <u>507-YMV</u> | <u>TOYOTA</u> | <u>COROLLA</u> | <u>2010</u> |
| CAR REGO | CAR MAKE | CAR MODEL | CAR YEAR |
| | | | <u>130,162</u> |
| INSPECTION COMPANY NAME |  | | ODO MILEAGE |
| <u>CRAIG STEWART</u> | <small>3630 4557 • 1508 Sandgate Rd, NUNDAH</small> | | <u>28/8/2023</u> |
| INSPECTOR NAME | INSPECTOR SIGNATURE | | DATE OF INSPECTION |