



268 Spence Street
Cairns City Queensland 4870
ABN: 57664152621
Tel: 0740516394
Email: karoautomotive@gmail.com

BILL TO:
Tropical Wonderland
Cairns QLD
Tel: 0430098888
Email: davidni88@yahoo.com.au

TAX INVOICE

Tax Invoice Number: 755
Date: 29/11/2023
Due Date: 29/11/2023

FOR:
Odometer: 257,215 Kms

Model: Toyota Camry
Reg No: 242 XQN
VIN: 6T153BK400X042987
Body Type: Sedan
Year: 2007

Description	Qty.	Unit Price	Amount
-------------	------	------------	--------

Carry out service and safety check.

Replaced front brake pads.

Machined front brake rotors.

Automatic transmission oil flush.

Secured battery hold down.

Replaced engine drive belt.

Inspect operation of park brake, transmission inhibitor switch, dash warning lights, horn, windscreen wipers and washers.

Inspect operation of all lights and reflectors.

Check seat belts for signs of wear and retractors for correct operation.

Drain engine oil and replace drain plug washer.

Change oil filter and refill with Castrol Magnatec 5w40 full synthetic premium grade oil.

Inspect exhaust system for security and leaks.

Check oil level and condition of transmission.

Inspect fuel lines for security and signs of leaks.

Inspect front and rear suspension for wear and security.

Inspect steering rack and components for wear and free play.

Inspect constant velocity drive shafts and boots.

Inspect all tyres including spare for uneven wear, correct pressure and report.

Inspect front and rear disc pads for wear.

Inspect front and rear disc brake rotors for scoring, thickness and report.

Dedust and adjust park brake.

Check wheel bearings for free play and adjustment.

Inspect brake fluid levels and condition.

Inspect battery for security, battery terminals for corrosion and testing.

Service and clean air filter housing, clean and inspect air filter element.

Inspect all drive belts for wear and correct tension.

Inspect cooling system hoses for signs of deterioration and coolant condition, pressure test cooling system and check for leaks.

Inspect power steering oil level.

Road test vehicle for engine response, correct brake and steering operation.

Front brake pads approximately new.

Rear brake pads approximately 50% worn.

MAG 5W-40 - CASTROL MAGNATEC PROFESSIONAL 5W-40	4.3	\$15.00	\$64.50
Z432 - RYCO OIL FILTER	1.0	\$23.05	\$23.05
SPW T - TOYOTA SUMP PLUG WASHER	1.0	\$3.00	\$3.00
IJC - INJECTOR CLEANER			\$11.00
WWA - WINDSCREEN WASHER ADDITIVE			\$1.00
9091602652 - ENGINE DRIVE BELT	1.0	\$83.10	\$83.10
DB1474-GCT - BENDIX FRONT BRAKE PADS	1.0	\$101.95	\$101.95
BCR - DISC ROTOR MACHINE	2.0	\$37.50	\$75.00
DOT 3 - TOYOTA DOT 3 BRAKE FLUID	2.0	\$17.00	\$34.00
WS AUTO OIL - TOYOTA WORLD STANDARD TRAMMISSION OIL	4.5	\$19.00	\$85.50
WSC - WORKSHOP CONSUMABLES			\$15.00
ENVRO FEE - ENVIRONMENTAL DISPOSAL FEE			\$5.00
LAB - LABOUR	3.0	\$110.00	\$330.00

Rocker cover gasket starting to leak.

Engine stabilizer mount broken.

Front and rear struts worn.

Front and rear link rods worn.

Subtotal	\$756.45
GST	\$75.65
Total	\$832.10
Paid	\$0.00
Balance Due	\$832.10

For Direct Deposit:
Account Name: KARO Automotive
BSB: 084970
Account: 237996424
Payment Reference: Invoice Number or Customer Name