



Service Tax Invoice Page 1 of 2

Doc #: MIADM336038

Customer No. 311519	Customer Name & Address Shakila Zia 33 Junction Road		Advisor George Tatas 28411	Colour White/Black	Team RETAIL M
Doc. Date 16/10/23	Moorebank NSW 2170		Year / Make / Model 20/MITSUBISHI/ES 2.4 Ptrl CVT AWD 7s Wag	Tag No. 50	
Reg. No. ELJ15K			Model No. ZL6M46	Carline OUTLANDER	Eng./Trans.
Stock No.			Chassis No.	Kilometres 59712	Prod. Date 10/02/20
Purchase Order No.	Driver	Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
	Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.
	Vehicle ID. JMFXTGF8WLZ007138	Engine No. 4J12 CK3966	Date & Time Promised 16/10/23 05:30pm	Time Received 07:30am	Quote Price
				Air	Pwr Turbo
Customer Email zarain.zia@gmail.com	Driver Email	Driver Mobile	Mobile Number 0475-101010		
Takata Recall nr	Takata Date 16/10/23	Rego Expiry Date	Roadside Number		
Warranty#	Extended Warranty Number	Extended Warranty Type	Extended Warranty Date		
Extended Expiry Kms	Recall Y/N				

Labour	Operation	Description	Amount
--------	-----------	-------------	--------

Job# 1	01MI70590060N09	60,000km/48mth service {SoldDate: 01/10/2020-, ModelYr: 2020-2020, OPT: With Distance Based Servicing}	72.39
--------	-----------------	--	-------

Customer Instructions:

Carried out 60,000km/48 month service as per handbook.

--- Under The Hood ---

Includes- Replaced engine oil and oil filter.

Checked air intake tubes and hoses.

Checked drive belt and adjusted tension as required.

Checked coolant level.

Inspected cooling system, hoses and connections.

Checked brake fluid level.

Checked and adjusted valve clearances.

Checked air cleaner element for clogging and damage.

Replaced brake fluid.

Checked battery electrolyte specific gravity, level and condition using specified tools.

Checked battery terminals for cleanliness and security.

Inspected EGR system.

--- Under The Vehicle ---

Inspected suspension and steering components for damage/wear.

Inspected ball joints, seals, bushes and boots.

Inspected drive shafts including CV boots.

Inspected automatic transmission fluid.

Inspected transfer case for oil leaks (in case of leakage, check the oil level).

Inspected rear differential for oil leaks (in case of leakage, check the oil level).

Inspected exhaust system for security and leaks.

--- Inside The Vehicle ---

Checked brake pedal travel.

Checked and adjusted park brake as required.

Checked lights, wiper/washers, horn and electrical systems.

Inspected seat belts.

Inspected air conditioning operation.

Replaced fresh air/pollen filter.

--- Outside The Vehicle ---

Checked condition and pressures of all tyres including spare.

Checked wheel alignment (visual inspection for tyre wear).

Checked wheel bearings for play.

Checked brake hoses and pipes for damage, corrosion and leaks.

Inspected brake pads and discs.

Inspected fuel pipes, hoses and connections for leaks.

--- Final Inspections and Road Test ---

Inspected the body of the vehicle for any damage.

Checked vehicle for outstanding recall or service campaigns.

Checked all electronic control system diagnosis output using



Service Tax Invoice				Page 2 of 2				Doc #: MIADM336038			
Customer No. 311519	Customer Name & Address Shakila Zia 33 Junction Road			Advisor George Tatas 28411	Colour White/Black	Team RETAIL M					
Doc. Date 16/10/23	Moorebank NSW 2170			Year / Make / Model 20/MITSUBISHI/ES 2.4 Ptrl CVT AWD 7s Wag			Tag No. 50				
Reg. No. ELJ15K				Model No. ZL6M46	Carline OUTLANDER		Eng./Trans.				
Stock No.	Purchase Order No.			Contract No.	Contract Name	Contract Exp. Kms	Exp. Date				
Home Phone		Business Phone		Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date	Warr. Exp. Date			
Vehicle ID. JMFXTGF8WLZ007138		Engine No. 4J12 CK3966		Date & Time Promised 16/10/23 05:30pm		Time Received 07:30am	Quote Price	Air Pwr Turbo			

manufacturer specified special tools.

Reset service indicator.

Road tested vehicle and reported any defects.

MI7803A109	AIR REFRESHER ASSY	1	59.90
MIMD050317	GASKET-DRAIN PLUG-14MM	1	3.29
MIAU901602	FLUID,BRAKE & CLUTCH, DOT4 (50	1	11.79
MIVS000587S	WINDSCREEN SOLUTION(SINGLE)	1	0.94
MI1230A184	OIL FILTER	1	22.07
POL	MAGNATEC PROF 10W-30		71.44
Misc:DAWPS	Diamond Advantage Price Variance		Warranty

<<< Total For Job 1 >>> **241.82**

Job# 2 87MI004 ROTATE & BAL WHEELS Tech(s): 37859 27.27

CARRY OUT ROTATE AND BALANCE OF WHEELS
CARRY OUT ASSESSMENT OF ALL FOUR TYRES.
 SELECT TWO BEST TYRES AND ROTATE TO THE FRONT IF NEEDED
 CARRY OUT BALANCE OF FRONT WHEELS REQUIRED

<<< Total For Job 2 >>> **27.27**

Job# 3 87MI032 SAFE T CHECK Tech(s): 37859 22.72

CARRIED OUT SAFE-T-STOP ULTIMATE BRAKE AND STEERING TEST
CHECK THE FRONT AND REAR WHEEL ALIGNMENT
Checked for dangerous side to side and front to rear brake
brake and handbrake imbalances.

<<< Total For Job 3 >>> **22.72**

Misc:FEL	FLEET ENVIRONMENTAL LEVY	15.00
Misc:FWS	FLEET WORKSHOP SUPPLIES	15.00
Misc:MRO	1 & 2 CENTS WRITE OFF	0.01

Total Labour	122.38
Total Parts	97.99
Total POL	71.44
Total Sublet	0.00
Total Misc	30.01
Total GST	32.18

Total Invoice 354.00

Total Amount Including GST

DID YOU KNOW YOU CAN NOW BOOK YOUR NEXT SERVICE ONLINE
 VISIT US AT www.mcgrathmitsubishi.com.au
DON'T FORGET TO CHECK OUT OUR MONTHLY SERVICE SPECIALS

Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:
 1. to cancel your service contract with us; and
 2. to a refund for the unused portion, or to compensation for its reduced value.
 You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service.

Banking Details: BSB # 014002 A/C # 838204197 - Use reference MIADM336038			
VEHICLE DELIVERY	Jobs & Notes Explained..... <input type="checkbox"/>	Cost Explained..... <input type="checkbox"/>	CSI Survey Explained <input type="checkbox"/>
Date:..... Time:..... Delivered By:..... Received By:.....			

Erase and Read all DTCs

2023.10.16

OT: E402005205 GF8WXTXPZR8 2020

All DTCs Erase and Read all DTCs x

System List		
Select	System Name	Results
<input checked="" type="checkbox"/>	MPI/GDI/DIESEL	OK
<input checked="" type="checkbox"/>	AT/CVT/A-MT/TC-SST	OK
<input checked="" type="checkbox"/>	AUTO CRUISE	-
<input checked="" type="checkbox"/>	4WS/Electric Power Steering	OK
<input checked="" type="checkbox"/>	ABS/ASC/ASTC/WSS	OK
<input checked="" type="checkbox"/>	SRS-AIR BAG	OK
<input checked="" type="checkbox"/>	Air Conditioner	OK
<input checked="" type="checkbox"/>	ETACS	OK

Diagnostic trouble code(s)		
Code	Name	Status


Check end and no DTC was detected.

Number of DTC(s):0

Home Up Print




THINK SAFETY Properly Adjusted Brakes Guarantee:
Optimal brake performance
+
A safer vehicle



SAVE MONEY Properly Adjusted Wheels Guarantee:
Optimal tyre wear
+
Better fuel economy




DRAG - ALIGNMENT TEST REPORT
PASS



■ = PASS ■ = FAIL ■ = INSPECTION RECOMMENDED

Vehicle No: _____
Examiner No: _____
Inspection Station No: SO3017
Calibration Due: OCT 2024
Serial No: PU052818
McGrath Mitsubishi Subaru
375 Hume Highway
Liverpool NSW 2170
Ph: 02 9600 5555



Signature
16.10.2023 09.20.25