

Tax Invoice

Inv. No. 73,762	Date 19/1/24	Order No. -	Sales ID -
------------------------	---------------------	--------------------	-------------------

Client Details
Edward Bagley

Vehicle Details	
Registration: CE-15-NE	Odo: 46942
Make/Model: MAZDA CX-8	Ref: 49231 Ma
Type: Station	Year: 2020
VIN#: JM0KG2WLA00302303	
Next service: Service Vehicle	
Due: 19/7/24	Kms: 51942

Account 24644	Home -	Work 8983 8073	Mobile 0405 191 243
----------------------	---------------	-----------------------	----------------------------

Work Done

Carried Out Service On Vehicle.
 Changed Engine Oil And Oil Filter.
 Checked All Fluid Levels And Topped Up As Necessary.
 Replace Air Filter.
 Replace Pollen Filter.
 Rotate Tyres.
 Reset Service Reminder.
 Carried Out 62 Point Safety Check On Vehicle.
 Carried Out Electronic Brake, Steering And Suspension Safety Test.
 Degreased And Washed Down Engine.
 Road Test Vehicle And Prepared For Collection.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	Service Vehicle	\$242.19	\$242.19	\$24.22	\$266.41
1	Oil Filter	\$23.34	\$23.34	\$2.33	\$25.67
4.5	Oil - Penrite Vantage Full Syn 5w30 Mv	\$12.15	\$54.68	\$5.47	\$60.15
1	Sump Plug Washer	\$4.09	\$4.09	\$0.41	\$4.50
1	Filter - Air	\$32.73	\$32.73	\$3.27	\$36.00
1	Filter - Cabin Air	\$77.93	\$77.93	\$7.79	\$85.72
1	Workshop supplies/ consumables	\$18.64	\$18.64	\$1.86	\$20.50
1	Environmental Requirements	\$15.00	\$15.00	\$1.50	\$16.50
Total Service Vehicle			\$468.60	\$46.85	\$515.45
1	Electronic Brake, Steering And Suspension Test	\$20.00	\$20.00	\$2.00	\$22.00
Total Electronic Brake, Steering And Suspension Test			\$20.00	\$2.00	\$22.00
1	Degrease	\$18.18	\$18.18	\$1.82	\$20.00
Total Degrease			\$18.18	\$1.82	\$20.00

Vehicle Report

Report -
Rear Tyres Low In Tread.

Financial Summary

Total (Ex. Tax)	\$506.78	Terms	Cash on delivery
Tax Total	\$50.67	Paid	\$0.00
Total (Inc. Tax)	\$557.45	Balance	\$557.45

Thank You For Your Business

Bank Details For Direct Payment:

Account Name: Sjp Automotive
Bsb: 085-005 Account Number: 94050-9907

Please Quote Invoice Number When Direct Depositing.

Were You Happy With The Service Provided Today? If So, Please Like And Recommend Prompt Auto Repairs On Facebook!
We Greatly Appreciate Your Custom.

Terms And Conditions Of Trade

1. Any Account Not Paid Within The Time Specified On The Invoice Or For More Than Sixty (60) Days Will Be Liable To Meet In Full The Seller's Debt Recovery, Legal Costs And / Or Commission And Internal Accounting Charges (recovery Fee) And Such Recovery Fees Will Be Added To The Buyers Account And Form Part Of The Principal Debt. 2. Title To Any Goods Purchased Does Not Pass At Law Until Payment In Full Of The Account To Which The Goods Relate. 3. Limited Warranty Will Apply To Reclaimed Parts Or Parts Not Supplied By Seller. Warranty Limitations May Also Apply To Standard Applications. 4. Acceptance Of Our Goods, Services Or Quotation Is Automatic Acceptance Of These Terms And Conditions.

Our Goods And Services Come With Guarantees That Cannot Be Excluded Under The Australian Consumer Law. For Major Failures With The Service, You Are Entitled: 1. To Cancel Your Service Contract With Us; And 2. To A Refund For The Unused Portion, Or To Compensation For Its Reduced Value. You Are Also Entitled To Choose A Refund Or Replacement For Major Failures With Goods. If A Failure With The Goods Or A Service Does Not Amount To A Major Failure, You Are Entitled To Have: The Failure Rectified In A Reasonable Time. If This Is Not Done, You Are Entitled To A Refund For The Goods And To Cancel The Contract For The Service And Obtain A Refund Of Any Unused Portion. You Are Also Entitled To Be Compensated For Any Other Reasonably Foreseeable Loss Or Damage From A Failure In The Goods Or Service. For Details Visit Repcoservice.com

NAB EFTPOS
PROMPT AUTO REPAIRS
COCONUT GROVE AU
MID: 52934791
TID: M5J825
Version: 0.10.03C

=====

CUSTOMER COPY

JAN 19, 24 13:07
BATCH: 000582
INV: 7370
STAN: 008555
ACCOUNT TYPE CREDIT
RRN: 000582007370
MASTERCARD
.....6685(m)
SALE AUD \$557.45

APPROVED 08
With Signature
APPROVAL CODE R22327

PLEASE RETAIN RECEIPT
FOR YOUR RECORDS



65 POINT

INSPECTION REPORT www.repcoservice.com

Prompt Auto Repairs

14 Travers St, Coconut Grove NT 0810

Ph: 08 8985 6733 E: admin@promptautorepairs.com

Customer Name: EDWARD BAGLEY

Rego #: CE-15-NE

Date: 19/01/2024

Technician Name: CAMERON

Job Card #: 73762

Odometer: 46942

Road Test		Comment	34	Suspension Bushes Front & Rear	OK
1	Noise and Vibrations	OK	35	Front Shock Absorbers	OK
2	Engine / Power Train Operation	OK	36	Front Bump Stops & Boots	OK
3	Air conditioning temperature	OK	37	Rear Shock Absorbers	OK
Under Bonnet			38	Rear Bump Stops & Boots	OK
4	Vehicle service history	OK	39	Spring Mounts / Shackles	OK
5	Engine Oil	NEW	40	Steering Arms & Linkages	OK
6	Automatic Transmission Fluid	OK	41	Ball Joints	OK
7	Power Steering Fluid	OK	42	Tie Rod / Rack Ends	OK
8	Engine Coolant	OK	43	Steering Box / Rack	OK
9	Coolant Leaks - Pressure Test	OK	44	Tyre Condition Front	ROTATED
10	Cooling System Hoses	OK	45	Tyre Condition Rear	ROTATED
11	Drive belts	OK	46	Tyre Pressure	OK 38 PSI
12	Timing Belt - Recorded History	OK	47	Wheel / Rim Condition	OK
13	Fuel System Service	OK	48	Wheel Bearings Front & Rear	OK
14	Brake Master Cylinder	OK	49	Front Brake Pads / Shoes	OK 30% WORN
15	Brake Fluid	OK	50	Front Brake Disc Rotors / Drums	OK
16	Clutch Fluid	N/A	51	Front Calipers / Wheel Cyls	OK
17	Clutch Hydraulics	N/A	52	Front Brake Hoses/Clips/Springs	OK
18	Clutch Cable / Linkages	N/A	53	Rear Brake Pads / Shoes	OK 50% WORN
19	Battery State of Health =	PASS 100 %	54	Rear Brake Disc Rotors / Drums	OK
20	Battery Terminals	OK	55	Rear Calipers / Wheel Cyls	OK
21	Battery Wiring - Visual	OK	56	Rear Brake Hoses/Clips/Springs	OK
22	Alternator Charge Rate	OK	Interior and Exterior		
Under Vehicle			57	Hand Brake Operation	OK
23	Engine Oil Leaks	OK	58	Dash & Instruments	RESET REMINDER
24	Transfer Oil Condition and Leaks	OK	59	Windscreen Wipers & Washers	OK
25	Power Steering Oil Leaks	OK	60	Windscreen & Glass	OK
26	G/Box Oil Condition & Leaks	OK	61	All Lights & Horn Tone	OK
27	Engine & Transmission Mounts	OK	62	Steering Wheel Grip	OK
28	Trans Linkage & Bushes	OK	63	Trim & Interior Fitting	OK
29	Diff Oil Condition & Leaks	OK	64	Body, Paint & Panel	OK
30	Exhaust System	OK	65	Bonnet Struts	OK
31	Universal Joints	OK	Other Items:		
32	Drive Shafts	OK	NEW AIR & POLLEN FILTERS.		
33	Evidence of Corrosion / Rust	OK			



TEST REPORT

—◇ BATTERY TEST ◇—

REGULAR FLOOD BATTERY

VOLTAGE: 12.47V
SELECT INPUT: CCA
RATED: 650A
MEASURED: 659A
INTERNAL R: 4.44mΩ

GOOD BATTERY

STATE OF HEALTH:



STATE OF CHARGE:



CLIENT:

TEST DATE: 2024/01/19


10:13:29

BY:



THINK SAFETY

Properly Adjusted Brakes Guarantee:
Optimal brake performance
+
A safer vehicle




BRAKE TEST REPORT

PASS

■ = PASS ■ = FAIL ■ = INSPECTION RECOMMENDED

SAVE MONEY

Properly Adjusted Wheels Guarantee:
Optimal tyre wear
+
Better fuel economy



DRAG - ALIGNMENT TEST REPORT

PASS

■ = PASS ■ = FAIL ■ = INSPECTION RECOMMENDED

Vehicle No: CE-15-NE 1
Examiner No:
Inspection Station No: AUG 2020
Calibration Due: PU107414
Serial No:

Prompt Auto Repairs
14 Travers Street
Coconut Grove NT 0810
Ph: 08 8985 6733

Signature



19.01.2024 08.55.49

EXPECT MORE

BRAKE STEERING SUSPENSION

SafetStop is a brake, steering and suspension safety test.

Detects dangerous side-to-side and front-to-rear brake imbalances that will cause a vehicle to spin out of control.

Checks wheel alignment on both front and rear axles, to guarantee maximum tyre performance.

Measures ride quality by testing the rebound of each shock absorber, from firm to soft.

Measures corner weight and acts as a weighbridge.

Gives an accurate printout of the vehicle's performance as "black and white" proof.



VEHICLE SAFETY TEST REPORT

SAFE-T-STOP

PLATETRONIC



Trust, Experience & Knowledge