Inspection		Pass	Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake	<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<<	0 0 0 0 0 0
2	CLUTCH (manual only)	0	0
3	TYRES Right front Right rear Left front Left rear	\$ \$ \$ \$ \$	00000
4	STEERING	Ø	0
5	SUSPENSION Front Rear		0 0 0
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	

Inspection		Pass	Fail
7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights	\$ \$ \$ \$ \$ \$	00000
8	DOORS (open, close, lock)	\checkmark	0
9	SPEEDOMETER	\checkmark	0
10	WARNING LIGHTS	\checkmark	0
11	REAR VIEW MIRRORS	\checkmark	0
12	SEAT BELTS	\sim	0
13	AIRBAGS	\checkmark	0

This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.

P	ASS	FAIL
(\checkmark	\bigcirc

1CA1HS	VOLKSWAGON	POLO	2014
CAR REGO	CAR MAKE	CAR MODEL	CAR YEAR
AUTOCARE PTY	168,871		
INSPECTION COMPAN	0D0 MILEAGE 30/08/23		
INSPECTOR NAME INSPECTOR		SIGNATURE	DATE OF INSPECTION

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.