



Government of **Western Australia**
Department of Transport

Driver and Vehicle Services

MR2772342

CERTIFICATE OF INSPECTION

Presented by: JOHN ROBERT BOND

Plate Number: 1DBM290

Make:	B.M.W.	Engine No:	A470I421N46B20BD
Model:	1 SERIES E87	Body Type:	CONVERTIBLE
Year:	2009	Transmission:	Automatic
VIN/Chassis No:	WBAUL52090VE85745	Odometer reading:	116460
Primary Colour:	SILVER/CHROME	M/C capacity:	
Class:	P	Primary fuel:	Petrol
Seats:	4	Axles:	2

Conditions: 002

Dimensions

Length	Wheelbase	Rear overhang
Width	Load space fwd	Fwd projection
Semi pin to front	Semi pin to rear	Semi S dimension
Drawbar length	Combination	Height
	Extreme axles	Tow coupling o/hang

Notes

Inspection Details

Site Details

Type: MOTOR VEHICLE INSPECTION OTHER	Site Number: 847U
Result: PASS	Site: JENSEN AUTOMOTIVE SERVICE & REPAIR
Date: 24/01/2024	Examiner: 1490

I the undersigned certify that I have caused the vehicle referred to in this certificate to be examined and tested in accordance with the written directions given by the Department of Transport WA and having regard to that examination and test do further certify that the vehicle complies with the regulatory requirements including written directions given by the Department of Transport WA as to its construction and equipment and that the vehicle is in a safe condition to be used on a road.

Examiner to sign



Government of **Western Australia**
Department of Transport

Driver and Vehicle Services

VEHICLE PASSED

Signature of Examiner *S. Main*

This inspection is valid for licensing purposes until 23/04/2024.