## **Uber** Carshare

## **Owner's Service Form**

Inspection		Pass	Fail	Insp	ection	Pass Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake	999999	00000	7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights	
3	CLUTCH (manual only)  TYRES  Right front  Right rear  Left front  Left rear	08888	0 00000	9 10 11 12	DOORS (open, close, I SPEEDOMETER WARNING LIGHTS REAR VIEW MIRRORS SEAT BELTS	
4	STEERING	0	0	13	AIRBAGS	$\checkmark$ $\circ$
5	SUSPENSION Front Rear	8	000			
6	WINDSCREEN  Large crack (+3cm)= Fail  Small crack (-3cm)= Pass  Front glass  Front wipers  Rear glass  Rear wiper (if available		0000000	m	his car was inspected lechanic listed below asses the checks liste	and satisfactorily
CAR F	20 dyear Dulo Cave ection company name aren ParMu	Sy V	Oni U OR SIGN	gwo L		2007  CAR YEAR  196216 KIM  ODO MILEAGE  214424  DATE OF INSPECTION

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.