Uber Carshare

Owner's Service Form

Inspection		Pass Fail	Inspection	Pass Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake		7 LIGHTS Headlights Turn indicator lights see note Brake lights Tail lights 8 DOORS (open, close, lock)	
2	CLUTCH (manual only)	0 0	9 SPEEDOMETER	V 0
3	TYRES Right front Right rear Left front Left rear	0 0 0 0 0	10 WARNING LIGHTS see note 11 REAR VIEW MIRRORS 12 SEAT BELTS	s 0 V 0
4	STEERING	√ 0	13 AIRBAGS	√ 0
5	SUSPENSION Front Rear	⋄ • •		
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	000000000000000000000000000000000000000	This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form. PASS FAIL	

CAR REGO DQV14D	CAR MAKE Suzuki	CAR MODEL Alto GL auto	CAR YEAR 2012
INSPECTION COMPA	ODO MILEAGE 191,650 km		
INSPECTOR NAME	INSP	ECTOR SIGNATURE	DATE OF INSPECTION
Colum Crawford	5		29/03/2024

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

Vehicle Service Record

- Engine flush, oil & filter (10W-40 synthetic)
- Gearbox oil & filter (FS ATF)
- Air filter
- Cabin filter
- · Spark plugs
- Front & rear wiper blades
- Windscreen washer fluid
- Tyre pressures

Notes

- Indicators do not self-cancel on left turn. Indicators work OK.
- Engine management light showing. Issue noted with ignition coil C. Ignition coil swapped and replaced, no change. Vehicle runs without issue.
- Damage to bodywork (variously) no impact to vehicle safety
- Radio head unit replaced

•