| inspection | | | Pass | Fail | In |
|------------|---|---|---------|--------|--------|
| | 1 | BRAKES Right front Right rear Left front Left rear Handbrake | 0000000 | 000000 | 7 |
| | 2 | CLUTCH (manual only) | 0 | 0 | 0 |
| | | | ~ | 0 | 9 |
| | 3 | TYRES | Ø | 0 | |
| | | Right front | 00000 | 00000 | 10 |
| | | Right rear | Ø | 0 | |
| | | Left front | Ø | 0 | 11 |
| | | Left rear | 0 | 0 | 12 |
| | 4 | STEERING | 6 | 0 | 13 |
| | 5 | SUSPENSION | ø | 0 | |
| | | Front | 6/ | 0 | |
| | | Rear | Ó | 000 | |
| | 6 | WINDSCREEN | 6/ | 0 | \int |
| | | Large crack (+3cm)= Fail | Ø | 0 | |
| | | Small crack (-3cm)= Pass | 6/ | 0 | |
| | | Front glass | 0, | 000000 | 1 |
| | | Front wipers | 6 | 0 | |
| | | Rear glass | O/ | 0 | |
| | | Rear wiper (if available | 0 | 0 | |

| Insp | ection | Pass/ Fail |
|------|---------------------------|------------|
| 7 | LIGHTS | 6,0 |
| | Headlights | 0/ O |
| | Turn indicator lights | Ø/ O |
| | Brake lights | 0/ O |
| | Tail lights | ø o |
| 3 | DOORS (open, close, lock) | 6/ 0 |
| • | SPEEDOMETER | 6 0 |
| 0 | WARNING LIGHTS | ø o |
| 1 | REAR VIEW MIRRORS | 60 |
| 2 | SEAT BELTS | 60 |
| .3 | AIRBAGS | 00 |

This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.

PASS

FAIL

| Y ZT 866 | Suzuki | Swift | 2012 |
|-----------------------------|------------------|------------|-----------------------|
| CAR REGO | CAR MAKE | CAR MODEL | CAR YEAR |
| INSPECTION COMPAN | tomotive Service | S | 000 MILEAGE 84 457 |
| INSPECTOR NAME Gaun Ross | | RSIGNATURE | DATE OF INSPECTION |

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.