


Inspection	Pass	Fail	Inspection	Pass	Fail
1 BRAKES	<input type="radio"/>	<input type="radio"/>	7 LIGHTS	<input type="radio"/>	<input type="radio"/>
Right front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Headlights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Right rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Turn indicator lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tail lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Handbrake	<input checked="" type="checkbox"/>	<input type="checkbox"/>	8 DOORS (open, close, lock)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2 CLUTCH (manual only)	<input type="radio"/>	<input type="radio"/>	9 SPEEDOMETER	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3 TYRES	<input type="radio"/>	<input type="radio"/>	10 WARNING LIGHTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Right front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	11 REAR VIEW MIRRORS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Right rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	12 SEAT BELTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	13 AIRBAGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
4 STEERING	<input checked="" type="checkbox"/>	<input type="radio"/>			
5 SUSPENSION	<input type="radio"/>	<input type="radio"/>			
Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
6 WINDSCREEN	<input type="radio"/>	<input type="radio"/>			
Large crack (+3cm)= Fail	<input type="checkbox"/>	<input type="checkbox"/>			
Small crack (-3cm)= Pass	<input type="checkbox"/>	<input type="checkbox"/>			
Front glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Front wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Rear glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Rear wiper (if available)	<input checked="" type="checkbox"/>	<input type="checkbox"/>			

This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.

PASS **FAIL**

CAR REGO	CAR MAKE	CAR MODEL	CAR YEAR
CEK28W	Suzuki	Alto GLX auto	2012
INSPECTION COMPANY NAME		ODO MILEAGE	
N/A		67,950 km	
INSPECTOR NAME	INSPECTOR SIGNATURE	DATE OF INSPECTION	
Colum Crawford		13/04/2024	

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

Vehicle Service Record

- Engine flush, oil & filter (10W-40 synthetic)
- Gearbox oil & filter (FS ATF)
- Air filter
- Cabin filter
- Spark plugs (iridium)
- Front wiper blades
- Windscreen washer fluid
- Tyre pressures
-

Notes

- Front brake pads and auxiliary drive belt to be replaced at next service
- Damage to bodywork (variously) – no impact to vehicle safety
- Radio head unit replaced
-
-