



Unit 2
42-44 Gavenlock Road
TUGGERAH NSW 2259

Phone: 4353-0488
FAX: 4353-0903
Mobile: 0411464796
Email: tuggerah@ultratune.com.au

If any of your contact details are incorrect, please inform us immediately so they may be corrected.

Contact: Glenn
Work:
Home:

Mobile: 0410467076
Email:

Bill to: Mr. MORTIMER
158 Woodbury Park Drive
MARDI NSW 2259

Payment Term: C.O.D.

Registration: DLQ49P

Make: TOYOTA

Model: HILUX

Manufacture Date: 2016 Recorded Rego. Due:

Odometer: 162394

Deliver to: m: 0410467076

Recall Details:

SAFETY NSW PINK SLIP recall by 26/02/2025.

MHS SERV 6M/10K recall at 172394, or by 11/10/2024

Code	Stock description or line text	RRP	Quantity	Unit	Line total
	Manufacturers Handbook Service				
	160000 km 96 months	\$140.000	2.60	\$140.000	\$364.00
LABOUR	LABOUR (P/H)	\$87.000	1.00	\$87.000	\$87.00
R2777P	RYCO FUEL FILTER CARTRIDGE	\$17.000	1.00	\$17.000	\$17.00
Z418	RYCO OIL FILTER	\$15.000	1.00	\$15.000	\$15.00
0970.01	HD DOT 4 CLEAR DBF	\$15.000	3.50	\$15.000	\$52.50
1385.01	SYNGEAR 75W85 SYNTHETIC	\$15.000	1.50	\$15.000	\$22.50
1385.01	SYNGEAR 75W85 SYNTHETIC	\$22.000	7.50	\$22.000	\$165.00
1381.01	SYNPOWER DT C2 0W30 SYNTHETIC	\$2.000	1.00	\$2.000	\$2.00
	SUMP PLUG WASHER	\$12.500	1.00	\$12.500	\$12.50
	ENVIROMENTAL LEVY	\$12.500	1.00	\$12.500	\$12.50
	SHOP SUPPLIES				
	*VEHICLE ON FLOOR				
	[/] Parking brake travel	Check/adjust	_OK_		
	[/] Driver's floor mat	Check security	_OK_		
	[/] Seatbelts/mountings	Check/report	_OK_		
	[/] Instruments/warning lamps	Check/report	_OK_		
	[/] Horn	Check/report	_OK_		
	[/] Interior lamps	Check/report	_OK_		
	[/] Wash/wipe systems	Check/report	_OK_		
	[/] Instrument illumination	Check/report	_OK_		
	[/] Direction indicators/hazards	Check/report	_OK_		
	[/] Lighting system	Check/report	_OK_		
	[/] Headlight levelling system	Check	_OK_		
	[/] Headlights	Check/report	_OK_		
	[/] Fuel tank breather system	Check	_OK_		
	[/] Fuel filler cap	Check/report	_OK_		
	*VEHICLE FULLY RAISED				
	[/] Engine oil leaks	Check/report	_OK_		
	[/] Engine oil	Drain/refill	_OK_		
	[/] Engine oil filter	Renew	_OK_		
	[x] Manual transmission oil leaks	Check/report	_N/A_		
	[x] Manual transmission oil	Check/top-up	_N/A_		
	[/] Automatic transmission fluid (ATF) lea	Check/report	_OK_		

ks



Unit 2
42-44 Gavenlock Road
TUGGERAH NSW 2259

Phone: 4353-0488
FAX: 4353-0903
Mobile: 0411464796
Email: tuggerah@ultratune.com.au

[/] Automatic transmission fluid (ATF) coolant hoses	Check/report	_OK_
[/] Front differential oil leaks	Check/report	_OK_
[/] Front differential oil	Drain/refill	_OK_
[/] Transfer box oil leaks	Check/report	_OK_
[/] Transfer box oil	Check/top-up	_OK_
[/] Steering joints	Check/report	_OK_
[/] Steering rack/box	Check/report	_OK_
[/] Steering column couplings	Check/report	_OK_
[/] Suspension joints/seals/gaiters	Check/report	_OK_
[/] Propshaft joints	Check/report	_OK_
Check tightness of propshaft bolts	Lubricate	_OK_
[/] Propshaft joints	Check/report	_OK_
[/] Drive shaft joints/seals/gaiters	Check/report	_OK_
[/] Rear differential oil leaks	Check/report	_OK_
[/] Rear differential oil	Drain/refill	_OK_
[/] Road springs	Check/report	_OK_
[/] Shock absorbers/mountings	Check/report	_OK_
[/] Exhaust system/mountings	Check/report	_OK_
[/] Brake pipes, hoses and connections	Check/report	_OK_
[/] Fuel pipes, hoses and connections	Check/report	_OK_
*VEHICLE HALF RAISED		
[/] Front brake pads	Check/report	_OK_
[/] Front brake discs	Check/report	_OK_
[/] Rear brake drums/linings/cylinders	Check/report	_OK_
[/] Brake fluid	Renew	_OK_
[/] Tyre condition	Check/report	_OK_
[/] Wheel balance	Check/report	_OK_
Front wheels only	Interchange	_OK_
[/] Road wheels	Check/adjust	_OK_
[/] Tyre pressures	Check/adjust	_OK_
*ENGINE BAY OPERATIONS		
[/] Battery condition/specific gravity	Check/report	_OK_
[/] Fuel pipes, hoses and connections	Check/report	_OK_
[/] Washer bottle(s)	Check/top-up	_OK_
[x] Clutch fluid reservoir	Check/top-up	_N/A_
[/] Power steering fluid	Check/top-up	_OK_
[/] Coolant/heater hoses	Check/report	_OK_
[/] Radiator	Check/clean	_OK_
Externally only, including air conditioning condensate		
[/] Coolant	Renew	_OK_
[/] Automatic transmission fluid (ATF)	Check/top-up	_OK_
[/] Air filter	Check/clean	_OK_
[/] Fuel filter	Renew	_OK_
[/] Diesel fuel sedimentor	Clean	_OK_
[/] Auxiliary drive belt(s)	Check/adjust	_OK_
[/] Exhaust emissions	Check/report	_OK_
[/] Air conditioning	Check/report	_OK_
[/] Air conditioning refrigerant level	Check	_OK_
*FINAL ITEMS CHECK		
[/] Towing hitch	Check/report	_OK_
*ROAD TEST VEHICLE		

UltraTune Tuggerah

A.B.N. 25282008899

TAX INVOICE 112259 : 11/04/2024



Unit 2
42-44 Gavenlock Road
TUGGERAH NSW 2259

Phone: 4353-0488
FAX: 4353-0903
Mobile: 0411464796
Email: tuggerah@ultratune.com.au

Vehicle handling/operation/performance Check/report OK

Service should be performed periodically. Periods for servicing is time or distance based and should be performed on which period elapses first, whether time or distance. Prolonging service periods beyond the recommended time may be damaging to the vehicle, reducing the vehicle's performance and reliability.
Carried out this service as per check list below in accordance with manufacturers specifications. (refer parts listed below).

THANK YOU

from the team at Ultra Tune Tuggerah.
If you have any questions or feedback about your recent experience at our centre, please feel free to contact us.

***Service Notes**

P/S/F headlight in-op replaced fuse but will blow again at some stage.
Front brake pads low approx 5,000 km left suggest doing before next service.



BSB: 082620 BSB Account: 576180702
BSB Account name: ULTRA TUNE TUGGERAH
Reference: MORT11-112259

Tax in this document: \$68.19
(Unit amounts marked "X" = tax free)

Total: \$750.00
Initial Payment: \$750.00
Outstanding: \$0.00

MORT11

A/C AUTHORISATION : AU23089 A/C REPAIR : L162776
ABN : 25282008899 LIC. MVRL : 55091