Uber Carshare

Owner's Service Form

Inspection		Pass Fail	ss Fail Inspection		Pass Fai
1	BRAKES Right front Right rear Left front Left rear Handbrake	88888	7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights	8 0 8 0 8 0
2	CLUTCH (manual only)	0 0	8	DOORS (open, close,	iock)
3	TYRES Right front Right rear Left front Left rear	8000	9 10 11	SPEEDOMETER WARNING LIGHTS REAR VIEW MIRRORS	
4	STEERING	Ø 0	12	SEAT BELTS	
			13	AIRBAGS	9/ 0
5	SUSPENSION Front Rear	800		Self - No.	
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available		This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form. PASS FAIL		
UU	AZ77 ItONDA		i\) 1°		2007
CAR R	36	CAR MODEL CITY SERVICE MECHANICS Queensberry St		MODEL IE S	CAR YEAR 167033 -
INSPE	M 引作。 BMAN YNAGMOO NOITO p:	Plbourne VIC 3051 9328 8618 rvicemechanics.com.au			ODO MILEAGE
1:5		SPECTOR SIGNATURE			28 (1/23

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.