

BEPO MOTORS
02 9949 6242

Ian Robinson
Prestige
02 9949 1711



Lic. No. MVRL54266
A.R.K.
AUTOMOTIVE

0420 940 445

HOLDEN HSV SUZUKI CITROEN SAAB PEUGEOT

Unit 3/2 Paton Place, Balgowlah NSW 2093

TAX INVOICE

Invoice Date
24 Nov 2023

Invoice Number
INV-19683

Reference
BMC41D

ABN
12 606 745 742

A.R.K. Automotive Pty Limited
Unit 3 2 Paton Pl
BALGOWLAH NSW 2093
AUSTRALIA
Ph: 0420 940 445

MVRL: 51103

Paul Immergluck
Unit 22 35-37 Quirk Rd
MANLY VALE NSW 2093
AUSTRALIA



Follow us on Facebook
[@arkautomotive](#)

Description	Qty	Unit Price	GST	Amount AUD
Hyundai I30 KMHDC51EMAU222932 Build - 10 2009 Kms - 154302 Carried out basic service . inspected vehicle . all fluid levels . brake fluid boiling level . air filter . fuel filter . coolant mixture . drive belts . spark plugs . washer jets . windscreen wipers . all exterior lights . tyres pressure and condition . brake pads and rotors . tighten all suspension / front & rear sub-frame bolts . torque wheel nuts lubricated all door latch's door locks and hinges and changed engine oil and filter .	1.00	179.99	10%	179.99
BG Engine oil performance flush "Heavy Duty"	1.00	24.98	10%	24.98
Ryco engine oil filter + sump plug washer	1.00	24.75	10%	24.75
Full synthetic 5w-30 Quality Engine Oil	4.25	14.50	10%	61.63
Engine air filter " Dirty" carried out replacement of dirty air filter. Cleaned air mass sensor and reset fuel trim codes	1.00	37.08	10%	37.08
Cabin air filter "Dirty Removed and replaced cabin filter"	1.00	28.82	10%	28.82
Workshop environment level fee	1.00	12.50	10%	12.50

Reverse light globe . Removed and replaced "Blown" Reverse light globe Left side	1.00	12.95	10%	12.95
Registration renewal inspection. Check road worthiness. Check tyres, warning lights, brakes, operational lights and critical suspension components for wear.	1.00	41.82	10%	41.82
Wheel alignment Front and Rear	1.00	65.00	10%	65.00
Kumho 205/55R16	2.00	150.00	10%	300.00
Complimentary hand wash and vacuumed	1.00	0.00		0.00
Windscreen fluid TopUp. Refill washer holding tank including blue concentrate. Complimentary	1.00	0.00		0.00
Stamp Service Book / Reset Service Light	1.00	0.00		0.00
Service report Engine and Wheels Test: battery Pass 720 CCA vs 800 CCA Brake fluid Pass Fail Coolant Pass Fail Front brake 40% worn . Good Rear brake 20% worn . Good Front tyres 100% worn. Good / Soon / Replaced now new Rear tyres 80% worn . Good				
			Subtotal	789.52
			Total GST 10%	78.96
			Total AUD	868.48

Due Date: 24 Nov 2023

PAYMENT ADVICE

To: A.R.K. Automotive Pty Limited
Unit 3 2 Paton Pl
BALGOWLAH NSW 2093
AUSTRALIA

BSB: 082-146
Acc: 771 40 2171

Customer	Paul Immergluck
Invoice Number	INV-19683
Amount Due	868.48
Due Date	24 Nov 2023
Amount Enclosed	

Enter the amount you are paying above