Owner's Service Form

Inspection		Pass	Fail	Inspection		Pass Fail
1	BRAKES Right front Right rear Left front Left rear Handbrake	88880	000000	8	LIGHTS Headlights Turn indicator lights Brake lights Tail lights DOORS (open, close, lock)	
2	CLUTCH (manual only)	V	0	9	SPEEDOMETER	V 0
3	TYRES Right front Right rear Left front Left rear	8880	00000	10 11 12	WARNING LIGHTS REAR VIEW MIRRORS SEAT BELTS	✓ ○✓ ○
4	STEERING	V	0	13	AIRBAGS	V 0
5	SUSPENSION Front Rear	0	000			
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	0000000	000000	This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form. PASS FAIL		

CAR REGO	CAR MAKE	CAR MODEL	CAR YEAR 2009	
DI72AW	Kia	Soul 2 manual		
INSPECTION COMP	ODO MILEAGE			
A-One Auto Motive	169,392 km			
INSPECTOR NAME	INSF	ECTOR SIGNATURE	DATE OF INSPECTION	
Colum Crawford	5		11/04/2024	

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

Vehicle Service Record

- Engine flush, oil & filter (5W-40 synthetic)
- Air filter
- · Cabin filter
- Spark plugs
- Gearbox replacement (75W-85 oil)
- Clutch replacement (flywheel machined)
- 4 x new 205/55 R16 tyres
- Front & rear wiper blades
- · Windscreen washer fluid
- Tyre pressures

Notes

- Minor damage to bodywork (variously) no impact to vehicle safety
- Radio head unit replaced
- •