



XCEED AUTOS PTY LTD T/as

CARWISE LDV

ABN 97 114 779 690 | MD 063467

4-8 Morley Ave, Kingswood, NSW 2747

service@carwise.com.au | www.carwiseldv.com.au

Phone (02) 4736 5500

Vehicle ID EYP01K		Description LDV Deliver 9 LWB HR Auto			Key Tag		Service Tax Invoice Number 17832		
Series				Model 6395DBCPG36400011			Page 1 of 3		Date 04/10/2023
Colour		Engine	Trans	VIN LSH14J7CXNA823969			Engine No.		Fuel Type
Paint Code	Radio Pin	Manufactured Date		Compliance Date	Manufacturer ID		Date First Registered		Stock Number
Account 51	Order Number		Deal No.	Salesperson		Dealer	Warranty Expiry 30/03/2026	Ext Warranty Expiry	Odometer 6203
Driver Name			Time In 08:00		Time Out 16:30		Date Out 04/10/2023		Phone

Booking: djalc - Caylan
 Advisor: djalc - Caylan
 Costing: salts - Sofie
 Finalised: djalc - Caylan
 RO: 36120
 Claim No:

Invoice To
 NIMBLE SERVICES PTY LTD

Job No	B/Code	Description	Units	Amount
1	R	Carried out 5,000km/6 month service as per handbook. --- Replacements --- Replaced engine oil and oil filter. Replaced rear axle fluid. Replaced fuel filter. --- Checks --- Inspected engine air filter element. Inspected pollen/cabin air filter element. Checked vehicle for outstanding recall or service campaigns. Checked for diagnostic trouble codes. Checked brake pedal travel and adjusted as required. Checked gear lever operation. Checked all interior lighting including dashboard warning lights. Inspected airbag surfaces for impairment or obstruction. Inspected seat belts operation and condition. Inspected and lubricated all latches, hinges and locks. Checked operation of all exterior lights. Checked windscreen washer and wiper blades. Checked windscreen washer fluid level. Checked brake fluid level. Checked engine coolant level. Checked cooling system hoses and fittings. Checked air conditioning system hoses and fittings. Checked intercooler pipe clamps (torque to 5 Nm). Checked drive belt/s and adjusted tension as required. Inspected vacuum hoses and connections. Inspected transmission fluid level. Inspected crankcase ventilation system. Inspected tyre condition/wear including spare and adjusted pressures as required. Inspected tyres as necessary. Checked and calibrated tyre pressure sensors (if fitted). Inspected brake pads and disc rotors. Inspected brake linings and drums (if fitted). Inspected brake lines, hoses and connections. Inspected front and rear suspension, tie rod ends, boot seals, ball joints. Inspected rear leaf spring bushings and end pads. Inspected rear differential for leaks. Inspected propeller shaft and couplings. Inspected park brake operation and adjusted as required. Inspected fuel lines, hoses and connections. Inspected electrical harnesses for correct routing and damage. Checked exhaust system for leaks and damage. Checked all visible underbody parts for leaks and damage. Carried out final inspection and road test.		

CARWISE LDV

ABN 97 114 779 690 | MD 063467

4-8 Morley Ave, Kingswood, NSW 2747

service@carwise.com.au | www.carwiseldv.com.au

Phone (02) 4736 5500



Vehicle ID EYP01K		Description LDV Deliver 9 LWB HR Auto			Key Tag	Service Tax Invoice Number 17832		
Series			Model 6395DBCPCG36400011		Page 2 of 3	Date 04/10/2023		
Colour	Engine	Trans	VIN LSH14J7CXNA823969	Engine No.	Fuel Type			
Paint Code	Radio Pin	Manufactured Date	Compliance Date	Manufacturer ID	Date First Registered	Stock Number		
Account 51	Order Number	Deal No.	Salesperson	Dealer	Warranty Expiry 30/03/2026	Ext Warranty Expiry	Odometer 6203	
Driver Name		Time In 08:00	Time Out 16:30	Date Out 04/10/2023	Phone			

Booking: djalc - Caylan
 Advisor: djalc - Caylan
 Costing: salts - Sofie
 Finalised: djalc - Caylan
 RO: 36120
 Claim No:

Invoice To
 NIMBLE SERVICES PTY LTD

Job No	B/Code	Description	Units	Amount	
		Labour		-\$8.91	
		Parts			
		Make	Part Item Code	Part Description	
		LDV	C00308847	TRAILRIDER OIL FILTER	
		LDV	c00260664	fuel filter oring	
		LDV	C00112937	FUEL FILTER	
		Quantity		Price Tax Excl.	
		1		\$18.62	
		1		\$15.87	
		1		\$79.67	
		Service Sundries	Description	Quantity	Price Tax Excl.
			Shop Supplies	1	\$22.73
			Environmental Levy	1	\$9.09
			EPX 80W90	4	\$51.08
			MP DX 5W30 3381200	5	\$72.75
			Tech List: wiffi		

Summary For Job 1

Job 1	Total (Excluding GST)	\$260.90
Job 1	Total (Including GST)	\$287.00

2 R RECOMMENDATIONS, BRAKE & TYRE REPORT
 FRONT BRAKES : 8MM
 REAR BRAKES : 7MM

 NSF TYRE : 8MM
 OSF TYRE : 8MM
 NSR TYRE : 8MM
 OSR TYRE : 8MM

 RECOMMENDATIONS :

 NEXT SERVICE AT :
 -
 NEXT SERVICE AT 35,000KMS OR OCTOBER 2024

Labour \$0.00

Tech List:

Summary For Job 2

Job 2	Total (Excluding GST)	\$0.00
-------	-----------------------	--------



XCEED AUTOS PTY LTD T/as

CARWISE LDV

ABN 97 114 779 690 | MD 063467

4-B Morley Ave, Kingswood, NSW 2747

service@carwise.com.au | www.carwiseldv.com.au

Phone (02) 4736 5500

Vehicle ID EYP01K		Description LDV Deliver 9 LWB HR Auto			Key Tag	Service Tax Invoice Number 17832		
Series			Model 6395DBCPG36400011			Page 3 of 3	Date 04/10/2023	
Colour	Engine	Trans	VIN LSH14J7CXNA823969		Engine No.	Fuel Type		
Paint Code	Radio Pin	Manufactured Date	Compliance Date	Manufacturer ID	Date First Registered	Stock Number		
Account 51	Order Number	Deal No.	Salesperson	Dealer	Warranty Expiry 30/03/2026	Ext Warranty Expiry	Odometer 6203	
Driver Name		Time In 08:00	Time Out 16:30	Date Out 04/10/2023	Phone			

Booking: djalc - Caylan
 Advisor: djalc - Caylan
 Costing: salts - Sofie
 Finalised: djalc - Caylan
 RO: 36120
 Claim No:

Invoice To
 NIMBLE SERVICES PTY LTD

Job No	B/Code	Description	Units	Amount
Job 2		Total (Including GST)		Not Applicable

Next Scheduled Service: 03/10/2024 Or 35000 Km

Warranties, Payments and Privacy Act Disclosure

Non-Approved Products: The owner/agent approves the use of non approved products/parts that are not recommended by the Vehicle Manufacturer. The use of non approved products/parts may affect the Vehicle and/or the Manufacturer's Warranty. These products/parts are identified as "Generic" and separate warranties may be offered from the Manufacturer of those products/parts. The customer/s hereby agree that in the event of default of payment of my debts that the company may disclose all information relating to my/our account to its collection agency for purpose of receiving any or all outstanding amounts.

The customer/s acknowledge that they have the opportunity to read the Dealership Privacy Act if so requested which is readily available upon demand for availability and in public view to the customer within the Dealership.

Direct Bank Payment Details

Account Name: Carwise

Bank: NAB

BSB: 082057

Account: 874763084

	"Cash On Delivery"
Invoice Total	-\$8.91
Total Labour	\$114.16
Total Parts	\$0.00
Total Part Sundries	\$155.65
Total Service Sundries	\$260.90
Invoice Total (Excluding GST)	\$26.10
GST	\$287.00
Invoice Total (Including GST)	

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.