



## TAX INVOICE

AMP28V honda crv

Invoice Date 14 Mar 2024

Invoice Number INV-4378

Reference 345309km

ABN 87 658 778 119 Downtown Billinudgel Automotive Pty Ltd 202 Middle Pocket Road BILLINUDGEL NSW 2483 AUSTRALIA

Description	Quantity	Unit Price	GST	Amount AUD
Carry out Log book service flush automatic trans oil clean headlights powersteer leak engine mount minor split Labour	2.00	99.00	10%	198.00
Engine oil	5.00	12.10	10%	60.50
Oil filter	1.00	14.30	10%	14.30
Top ups/Waste	1.00	11.00	10%	11.00
Automatic trans oil	1.00	71.50	10%	71.50
Rego inspection	1.00	46.20	10%	46.20
		INCLUDES (	GST 10%	36.50
		TOTAL AUD		401.50

Due Date: 14 Mar 2024

Bank Account Details Suncorp Bank BSB: 484-799 ACC: 48 098 1826

# **PAYMENT ADVICE**

To:

Downtown Billinudgel Automotive Pty Ltd 202 Middle Pocket Road BILLINUDGEL NSW 2483 AUSTRALIA Customer AMP28V honda crv Invoice Number INV-4378

Amount Due 401.50

Due Date 14 Mar 2024

Amount Enclosed

Enter the amount you are paying above

### Inspection Station e-Safety Check Report



14/3/24, 3:39 pm

spection report shows if the vehicle has passed a NSW Safety Check. It is not a comprehensive report on the vehicle's mechanical ation. Once passed the report is valid for 6 months. However, for the purpose of selling the vehicle the report must not be older than 42 as. For more information contact Transport for NSW on 13 22 13 or visit rms.nsw.gov.au

Brake-Testa
Millennium
5/W Version: 2.4
12Mar2024 08:53 D/S
Next Cal Due 13Mar2025
Circuitlink

-S/N ME8817

3347305 VNow Pass

3240

wntown Billinudgel Automotive Bonanza Drive

LINUDGEL, NSW 2483

gistration Renewal

Inspection date: 14/03/2024 Amount paid: 46.00

Vehicle details:

Number plate:

AMP28V

Class:

**Light Vehicle** 

Make:

HON

Model:

cord of the vehicle's compliance with the inspection standards of the Rules for Authorised

CR-V

Odometer reading: 345309

Compliance date: 2 /2001

Brake - Testa Millennium 5/W Version: 2.4

Date 12Mar2024 08:54 D/S Next Cal Due 13Mar2025 Examiner F13943

Examiner E13943 Rego AMP28U

Test Number 2929

Foot Brake Test

Vert axis=0.5s per div Pedal Max=217N (Pk=205N)

200N

inspection.

E13943

#### Problem

a i) Headlights (high/low beam) not working or damaged

a ii) Front park lights not working or damaged

400

newing registration is easy. Go to myRTA.com
puirements

Registration renewa

CTP greenslip. You can TA.com

Registration renewal payment options

Complete renewal requirements then:

**I**PAY


Visit myRTA.com or call 1300 360 782 to obtain BPAY details.

Internet payments: Visit myRTA.com to pay using a valid credit card.

Telephone payments: Phone 1300 360 782 to pay

using a valid credit card.

In person: At your nearest registry.



Signature:

Circuitlink -S/N ME8817-

Speed of Test = 41km/h Light Veh, Foot Brake

## **Authorised Inspection Station e-Safety Check Report**



This inspection report shows if the vehicle has passed a NSW Safety Check. It is not a comprehensive report on the vehicle's mechanical condition. Once passed the report is valid for 6 months. However, for the purpose of selling the vehicle the report must not be older than 42 days. For more information contact Transport for NSW on 13 22 13 or visit rms.nsw.gov.au

e-Safety Check number: AS3347305

e-Safety Check status: Fail/Now Pass

Inspection date: 14/03/2024

**Downtown Billinudgel Automotive** 

**BILLINUDGEL, NSW 2483** 

46.00

Inspection station:

S08240

Number plate:

Class:

**Amount paid:** 

Vehicle details:

AMP28V **Light Vehicle** 

Address:

16 Bonanza Drive

Make: HON

Model:

CR-V

Reason for inspection: Registration Renewal

Odometer reading: 345309 Compliance date: 2/2001

Comment:

Number:

Name:

**Examiner's certification:** 

I certify that the report is a true record of the vehicle's compliance with the inspection standards of the Rules for Authorised

Inspection Stations at the time of inspection.

Examiner's signature:

Examiner's number:

E13943

Reason/s for failure:

Component

**Problem** 1.Lights - Rule 106.02

2.Lights - Rule 106.02

a i) Headlights (high/low beam) not working or damaged a ii) Front park lights not working or damaged

### Renewing registration is easy. Go to myRTA.com

#### Renewal requirements

Vehicle requires a valid CTP greenslip. You can then pay online at myRTA.com

Registration renewal payment options

Complete renewal requirements then:

Visit myRTA.com or call 1300 360 782 to obtain BPAY details.

Internet payments: Visit myRTA.com to pay using a valid credit card.

Telephone payments: Phone 1300 360 782 to pay using a valid credit card.

In person: At your nearest registry.



\*\*\*\*\*\*\*\*\*

DOWNTOWN AUTO
BILLINUDGEL QLD 4224

MID: 215700424035992

TID: 10050859

Version: 0.9.610

CUSTOMER COPY

MAR 15, 24 12:31 BATCH: 000466

INV: 6865

STAN: 008089

ACCOUNT TYPE CREDIT

RRN: 008089123122

V15A A00000000031010

Visa CREDIT

..0617(t)

SALE AUD \$401.50

APPROVED

08

APPROVAL CODE 411005

ARQC: 7C98AF03842CB1FF

APSN:00 ATC:0122

方方方方方方方方方方方方方方方方方方方方方方方方方方

PLEASE RETAIN RECEIPT FOR YOUR RECORDS