

HOBART DEALERSHIP PT
235 ARGYLE ST
HOBART TAS 7000

...com.au

LMCT: 6056

TID P3647737
MID 04426581
DATE/TIME 02/02/24 08:52

RRN 020852026465
STAN 026465 AUTH 697265
CARD 0687 CR(T)
MASTERCARD
DEBIT MASTERCARD
AID A0000000041010
TVR 0000008001 ATC 0017
ARQC D0D9FC94FA666D90

PURCHASE AUD 607.00

APPROVED 0000

CUSTOMER COPY

SERVICE TAX INVOICE

REPAIR ORDER No: JCB0042226	PAGE: 1
C1 Customer (Cash)	

DATE: 01/02/2024	TIME IN: 7:50 AM	TIME OUT: 12:10 PM	KILOMETRES: 55381	ADVISER: KLR
VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety F			MONTH/YEAR 06/2021	AIR:
REG. No: J90VJ	STOCK No: US02128	SELLING DEALER:		
VIN: KNAF251CMN5118815		ENGINE No: G4NAMH506835		
COLOUR/TRIM Clear White (UD)/Graphite/Saturn Black (WK)			ORDER No:	
WAR. EXP: 30/08/2028	WAR. KM: 999999	EXT.WAR.EXP: 31/03/2033	EXT.WAR.KM: 175000	RDR Date: 28/08/2021

JOB	DESCRIPTION	PRICE	QTY/HR	AMOUNT
JOB 1	CARRY OUT 60,000KM/48 MONTH KIA SERVICE (MYR) Carried out 60,000km/48 month Kia Service. Added Genuine Oil System Cleaner Replaced Engine Oil with 5W/30 A5 Replaced Oil Filter with Genuine Filter Replaced Sump Plug Washer with Genuine Washer Added Genuine Fuel Additive Replaced Brake Fluid with Genuine Brake fluid Replaced Cabin Pollen Filter with Genuine Filter Replaced Fuel Tank Air Filter with Genuine Filter Inspected Engine Air Filter Inspected Cooling System Inspected Drive Belts Inspected Vacuum and Crankcase Ventilation Hoses Inspected Fuel lines & hoses Inspected Exhaust System Visually Inspected Battery Condition Inspected Brake Lines, Hoses etc Inspected Park Brake and adjusted where necessary Inspected Disc Brakes and Disc Pad Condition, registered all measurements Inspected Power Steering System (For MDPS, inspected Steering Rack etc.) Inspected Tyres (pressure & tread) Inspected Driveshaft Boots Inspected Front & Rear Suspension Inspected A/C Compressor Inspected Air Conditioner Refrigerant Inspected Vapour Hose, Fuel and Filler Cap Inspected Valve Clearance (Audible Only) Checked for Outstanding Service Campaigns and Recalls Connected Kia Diagnostic System (KDS) and check for DTC's Kia Roadside Assistance Activated Performed Quality Control Road Test after completing service Topped up Windscreen Washer fluid with Genuine windscreen washer fluid Carried out Kia Vehicle Inspection Checklist			270.22
PRT	2151323001 GASKET-ENGINE OIL PAN DRAIN		1	1.39
PRT	2630035505 FILTER ASSY-ENGINE OIL		1	9.45
PRT	31453M6100 VALVE-CANISTER CLOSE		1	75.96
PRT	3426889 KIA BRAKE FLUID 500ML DOT4		2	20.20

***** CONTINUED *****

CASH MASTERCARD VISA CARD EFTPOS Payment Received with Thanks on the ___/___/___



SERVICE TAX INVOICE

Hobart Kia
 Brisbane Street, Hobart TAS 7000
 (03) 6213 5370 E: service@hobartkia.com.au
 www.hobartkia.com.au
 ABN: 54 687 035 787 ACN: 631 123 049 LMCT: 6056
 Hobart Dealership Pty Ltd T/A Hobart Kia

REPAIR ORDER No: JCB0042226	PAGE: 2
C1 Customer (Cash)	

CUSTOMER: BENJAMIN JAMES MCKEAN 23 Salacia Ave HOWRAH TAS 7018		DATE: 01/02/2024	TIME IN: 7:50 AM	TIME OUT: 12:10 PM	KILOMETRES: 55381	ADVISER: KLR	
VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety f					MONTH/YEAR 06/2021	AIR:	
REG. No: J90VJ	STOCK No: US02128	SELLING DEALER:					
CUSTOMER No: 31848	VIN: KNAF251CMN5118815	ENGINE No: G4NAMH506835					
CONTACT NAME: Mr Benjamin Mckean		COLOUR/TRIM Clear White (UD)/Graphite/Saturn Black (WK)			ORDER No:		
CONTACT NUMBERS: M:0437507047		WAR. EXP: 30/08/2028	WAR. KM: 999999	EXT.WAR.EXP: 31/03/2033	EXT.WAR.KM: 175000	RDR Date: 28/08/2021	

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
PRT 97133F2000 FILTER ASSY-AIR		1	51.61
PRT AK0C0WS005 WINDSCREEN WASHER SOLUTION		1	2.68
PRT C0A39APK00 OIL SYSTEM CLEANER		1	10.00
PRT KMF300 INJECTOR CLEANER-250ML		1	8.59
CON High Quality 5W-30			60.12
MIS Enviro Waste Recovery KIA			10.00
MIS Shop Supplies KIA			15.00
MIS ROADSIDE ASSIST LEVY			16.60
JOB 1 SUBTOTAL			551.82

JOB DETAILS
 JOB 2 SURVEY
 Thank you for servicing with Hobart Mitsubishi & Kia.
 You will receive a survey via either email or SMS.
 We would greatly appreciate your time in filling this survey out as all feedback positive and negative will help us improve our service to all of our valued customers.
 By filling out the survey you will go into the draw to win prizes from the manufacturer.

JOB 2 SUBTOTAL **NO CHARGE**

JOB DETAILS
 JOB 5 NO SERVICE BOOK

JOB 5 SUBTOTAL **NO CHARGE**

**** Next service due: 01/02/2025 or odometer reading: 75000 whichever comes first.

LABOUR	\$270.22
OILS	\$60.12
PARTS	\$179.88
MISCELLANEOUS	\$41.60
SUBTOTAL	\$551.82
GST	\$55.18
TOTAL INCLUDES GST	\$607.00

***** CONTINUED *****

CASH
 MASTERCARD
 VISA CARD
 EFTPOS
 Payment Received with Thanks on the ___/___/___



SERVICE TAX INVOICE

Hobart Kia
 Brisbane Street, Hobart TAS 7000
 (03) 6213 5370 E: service@hobartkia.com.au
 www.hobartkia.com.au
 ABN: 54 687 035 787 ACN: 631 123 049 LMCT: 6056
 Hobart Dealership Pty Ltd T/A Hobart Kia

REPAIR ORDER No: JCB0042226	PAGE: 3
C1 Customer (Cash)	

CUSTOMER: BENJAMIN JAMES MCKEAN 23 Salacia Ave HOWRAH TAS 7018		DATE: 01/02/2024	TIME IN: 7:50 AM	TIME OUT: 12:10 PM	KILOMETRES: 55381	ADVISER: KLR
VEHICLE: MY22 Kia Cerato S Auto Hatch with Safety F					MONTH/YEAR 06/2021	AIR:
REG. No: J90VJ	STOCK No: US02128	SELLING DEALER:				
CUSTOMER No: 31848	VIN: KNAF251CMN5118815	ENGINE No: G4NAMH506835				
CONTACT NAME: Mr Benjamin Mckean		COLOUR/TRIM Clear White (UD)/Graphite/Saturn Black (WK)			ORDER No:	
CONTACT NUMBERS: M:0437507047		WAR. EXP: 30/08/2028	WAR. KM: 999999	EXT. WAR. EXP: 31/03/2033	EXT. WAR. KM: 175000	RDR Date: 28/08/2021

JOB DETAILS	PRICE	QTY/HRS	AMOUNT

PRINTED 01/02/24 09:45:36

CASH MASTERCARD VISA CARD EFTPOS Payment Received with Thanks on the ___/___/___

If you wish to pay your invoice electronically please use the following account and use your Customer Number as a payment
 Account Name: Hobart Dealership Pty Ltd
 BSB: 334-040
 Account: 555-308-957

Vehicle Inspection Checklist



Each item should be checked off

- GREEN = INSPECTION RESULT OK
- YELLOW = WILL REQUIRE ATTENTION SOON
- RED = REQUIRES IMMEDIATE ATTENTION
- WHITE = NOT APPLICABLE

PRE-INSPECTION

- Check for Outstanding Campaigns and Recalls
- Check Capped Price Service Schedule

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------

WALKAROUND INSPECTION

- Add Genuine Oil System Cleaner (if applicable)
- Replace Genuine Fuel Additive
- Inspect Vapour Hose, Fuel and Filler Cap
- Inspect Exterior Lighting

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------

INTERIOR INSPECTION

- Inspect or Replace Cabin Pollen Filter
- Inspect Interior Lighting and horn operation
- Inspect Brake Pedal operation and switch adjustment
- Inspect Clutch Pedal operation (if applicable)
- Inspect All Electrical Systems incl. A/C operation
- Inspect Power Window operation
- Inspect Seat Belt operation
- Inspect Washer and Wiper arm operation

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------

ENGINE BAY INSPECTION

- Replace Spark Plugs (if required)
- Inspect cooling system operation and replace Engine Coolant (if required)
- Inspect or Replace Engine Air Filter
- Inspect Drive Belts
- Inspect Plenum chamber and all water drain valves (clean if required)
- Inspect Valve Clearance (Audible check)
- Inspect A/C Compressor operation and A/C Refrigerant
- Visually Inspect Battery Condition
- Inspect Brake and Clutch Fluid condition
- Inspect Vacuum and Crankcase Ventilation Hoses
- Inspect Intercooler and Intake Hoses (if applicable)
- Top up Windscreen Washer fluid

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------

UNDERBODY INSPECTION

- Replace Engine Oil and Oil Filter *4L 5W-30*
- Replace Brake and Clutch Fluid (if required)
- Replace Fuel Filter (if required)
- Inspect or Replace Fuel Tank Air Filter (if applicable)
- Inspect or Replace Rear Differential Oil (if applicable)
- Inspect or Replace Transfer Case Oil (if applicable)
- Inspect or Replace Manual Transmission Fluid (if applicable)
- Inspect or Replace Automatic Transaxle Fluid (if applicable)
- Inspect Propeller Shaft - Clean, Tighten (if applicable)
- Inspect Tyre Pressures & Tread condition, register all tread depths *3.2*
- Rotate & Balance Tyres (if required)
- Inspect Brake Lines, Hoses etc
- Inspect Disc Brakes and Disc Pad Condition, register all measurements
- Inspect Park Brake and adjust if necessary
- Inspect Driveshaft Boots
- Inspect Power Steering System (For MDPS, inspect Steering Rack etc.)
- Inspect Steering Linkages and Boots
- Inspect Front & Rear Suspension
- Inspect Fuel Lines & Hoses
- Inspect Exhaust System
- Inspect Chassis, Body Nuts/Bolts

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------


FINAL INSPECTION

- Connect Kia Diagnostic Service Tool and check for DTC's
- Kia Roadside Assist Activation
- Fit Service Reminder Sticker and Reset Service Indicator on Dash Display
- Perform Quality Control Road Test after completing service

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------


Customer Name Benjamin Mokean
 Date 1-2-24
 Service Performed 60,000 km Service
 Odometer 55,381
 VIN # KNAF2S1C9N5118815
 RO No. 42226

EXTERIOR VEHICLE INSPECTION




Please note any scratches, dents or dings on the diagram above

CHECK TYRES/MEASURE TREAD DEPTH



BRAKE PAD LINING THICKNESS



Technician Signature [Signature]

Service Manager Signature _____