## **Uber**Carshare

MECHANICS
3630 4557 • 1508 Sandgate Rd, NUNDAH

INSPECTION COMPANY NAME

## **Owner's Service Form**

134303

ODO MILEAGE

Inspection	Pass Fail	Inspection	Pass /Fail	
1 BRAKES  Right front  Right rear  Left front  Left rear  Handbrake		7 LIGHTS  Headlights  Turn indicator lights  Brake lights  Tail lights		
2 CLUTCH (manual only)	0 0	<ul><li>8 DOORS (open, close, loc</li><li>9 SPEEDOMETER</li></ul>	sk) Ø 0	
3 TYRES Right front Right rear Left front	8888	10 WARNING LIGHTS 11 REAR VIEW MIRRORS		
Left rear  4 STEERING	80	12 SEAT BELTS  13 AIRBAGS		
5 SUSPENSION Front Rear	800			
6 WINDSCREEN  Large crack (+3cm)= Fail  Small crack (-3cm)= Pass  Front glass  Front wipers  Rear glass  Rear wiper (if available		mechanic listed below a	This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form.  PASS FAIL	
CAR RECOUNTED CAR MAKE		GET Z  CAR MODEL	2010 CAR YEAR	

INSPECTOR NAME INSPECTOR SIGNATURE DATE OF INSPECTION