UberCarshare

INSPECTOR NAME

Ali Raza

Owner's Service Form

DATE OF INSPECTION

18/12/2023

Inspection		Pass	Fail	Insp	ection	F	Pass	Fail
1	BRAKES Right front Right rear Left front Left rear	\$ \$ \$ \$	0 0 0 0 0	7	LIGHTS Headlights Turn indicator lights Brake lights Tail lights		888	0 0 0 0
	Handbrake	\otimes	0	8	DOORS (open, close,	lock)	\otimes	0
2	CLUTCH (manual only)	0	0	9	SPEEDOMETER		\oslash	0
3	TYRES	\oslash	\circ					
	Right front	\otimes	\circ	10	WARNING LIGHTS		\bigcirc	0
	Right rear	\bigcirc	\circ	11	REAR VIEW MIRRORS	2	\bigcirc	0
	Left front	\otimes	0		KEAK VIEW WIIKKOK	•	•	
	Left rear	\otimes	0	12	SEAT BELTS		\bigcirc	0
4	STEERING	\bigcirc	0	13	AIRBAGS		\otimes	0
5	SUSPENSION	\otimes	0					
	Front	\otimes	\circ					
	Rear	\otimes	0					
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	800888	000000	m	his car was inspected lechanic listed below asses the checks list	and satisfacto	rily	
CAR R	REGO CAR MAKE 1ZL6IM	TOYO	ТА	CAR N	MODEL VITZ	CAR YEAR	2018	3
INSPECTION COMPANY NAME MALIK AUTOMOTIVE						ODO MILEAGE	730	57

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.

INSPECTOR SIGNATURE